

## SALES REPORT: CATERPILLAR 309 CR - SN GW900375 - Year 2020

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

### MACHINE DATA

---

**Model:** 309 CR

**Family:** MINI EXCAVATOR

**Serial Number:** GW900375

**Order Number MU/MM:** MU00800156

**Construction year:** 2020

**Hour meter:** 6146

**General residual conditions Truck/Tyres:** 50 %

**Machine main application:** Basic application

**Location:** Conto deposito c/o Fornitore

**Rating:** ★★☆☆☆

**Public price:** Ask

### MACHINE CONFIGURATION

---

● Machine type Standard ● Boom type Triple boom ● Boom check valves ● Stick check valves ● Bucket Standard Get Teeth 3 ● Truck type Fixed ● Blade ● Cabin type Fixed standard ● Product Link ● 9500 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual

**MACHINE PHOTOS**

---

◆ Il contaore è:

Funzionante





---

◆ Painting Conditions Poor

---

◆ Counterweight conditions: Good

---

◆ Frame/Bumper conditions: Good

---

**TRUCK**

---

◆ Sprockets residual: 50

---

◆ Front idler wheel residual: 50

---

◆ Rollers upper/bottom residual: 50

---

◆ Chains residual: 50

---

**Right side**

---

◆ Door conditions (right): Poor

---

◆ Spar conditions: Good

---

**Left side**

---

◆ Door conditions (left): Good

---

◆ Door conditions (left): Good

---

◆ Spar conditions (left): Good

---

◆ Hood/Armor bottom conditions: Present and bash

---

**Functionality**

---

### Engine & electrical system functionality

---

◆ In quale stato è stata visionata la macchina:	Accesa e provata per ispezione
◆ Engine working conditions:	Good
◆ Engine with oil leaks:	Yes
◆ Engine presents blowby:	No
◆ Oil-Water presence:	No
◆ Engine present smokiness:	No
◆ Radiator conditions:	Good
◆ Starter motor conditions:	Good
◆ Batteries/Cables conditions:	Good
◆ Presence of electrical fault:	Si

### Functionality drive and rotation

---

◆ Hydraulic pump conditions:	Good
◆ Engine rotation conditions:	Good
◆ Engine travel conditions:	Good
◆ Final drives conditions:	Good
◆ Hydraulic joint conditions:	Good
	Presence of leaks : No
◆ Hydraulic joint conditions:	Good
	Presence of leaks : No

**Linkage Group**

---

◆ Hydraulic conditions linkage group: No

---

◆ Boom structure: Good

Photos

Presence of welding/cracks : Yes



◆ Stick structure: Good

Presence of welding/cracks : No

---

◆ Flexible pipes conditions: Poor

---

◆ Boom cylinders conditions: Poor

Leaks : No

---

◆ Stick cylinder conditions: Poor

Leaks : Yes

---

◆ Bucket cylinder conditions: Good

Leaks : Yes

---

- ◆ Pins & Bushings boom conditions: Poor

---

- ◆ Pins & Bushings stick conditions: Good

---

- ◆ Pins & Bushings bucket conditions: Poor

---

- ◆ Bucket & Get conditions: Good

---

- ◆ Quick Coupler conditions: Good

---

- ◆ Auto Lube working conditions: No

---

### Cabin and Tools

---

- ◆ Conditions internal cabin: Good

---

- ◆ Flashing presents issues: No

---

- ◆ Lights & Windshield present issues: Not presents

---

- ◆ Air conditioning is working: Non funzionante

---

- ◆ Back & side camera conditions: Present and functioning

---

### Check 81/2008

---

- ◆ Glass conditions: Excellent - no needs repair

---

- ◆ Lights conditions: Excellent - no needs repair

---

- ◆ Rear view mirrors conditions: Excellent - no needs repair

---

- ◆ Stepladders & handrails conditions: Good

---

- ◆ Cameras conditions: Excellent - no needs repair

---

◆ Flashing conditions:	Not functioning
◆ Safety belt conditions:	Present and valid
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	No
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	No
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	No
◆ Boardwalk presence:	Present and functioning

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.