

**SALES REPORT: NEW HOLLAND NHE235#KFNHK - SN YU04-00### - Year 2005**

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

**GENERAL CONDITIONS**

---

**MACHINE DATA**

---

**Model:** NHE235#KFNHK

**Family:** MEDIUM EXCAVATOR

**Serial Number:** YU04-00###

**Order Number MU/MM:** MU00804154

**Construction year:** 2005

**Hour meter:** 13168

**General residual conditions Truck/Tyres:** 20 %

**Machine main application:** Basic application

**Machine availability date :** 24/12/2025

**Location:** Coming in

**Rating:** ★★☆☆☆

**Public price:** Ask

**MACHINE CONFIGURATION**

---


● Machine type Standard ● Boom type Mono boom ● Boom check valves ● Plant features Hammer line linea drenaggio ● Bucket Standard 1300mm Get Teeth ● Truck type Fixed ● Blade ● General Truck Residual 20% ● Cabin type Fixed standard ● 25600 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual ● AVAILABLE FROM MARCH

## MACHINE PHOTOS


---


◆ Il contaore è:

Funzionante











## GENERAL APPEARANCE

---

- ◆ Painting Conditions Good

---

- ◆ Counterweight conditions: Good

---

- ◆ Frame/Bumper conditions: Poor

---

## TRUCK

---

- ◆ Sprockets residual: 20

---

- ◆ Front idler wheel residual: 20

---

- ◆ Rollers upper/bottom residual: 20

---

- ◆ Chains residual: 20

---

### Right side

---

- ◆ Door conditions (right): Good
  - ◆ Spar conditions: Good
  - ◆ Other issues: Vari graffi con ruggine
- 

### Left side

---

- ◆ Door conditions (left): Good
  - ◆ Door conditions (left): Good
  - ◆ Spar conditions (left): Good
  - ◆ Other notes: Scalette con ammaccature Pedana lato cabina con ammaccatura
  - ◆ Hood/Armor bottom conditions: Present and intact
- 

### Functionality

---

#### Engine & electrical system functionality

---

- ◆ In quale stato è stata visionata la macchina: Accesa e provata per ispezione
  - ◆ Engine working conditions: Good
  - ◆ Engine with oil leaks: No  
If Yes, where : Trasudi
  - ◆ Engine presents blowby: No
  - ◆ Oil-Water presence: No
-

- ◆ Engine present smokiness: No  

---
- ◆ Radiator conditions: Good  

---
- ◆ Starter motor conditions: Good  

---
- ◆ Batteries/Cables conditions: Poor  

---
- ◆ Presence of electrical fault: No  

---

### Functionality drive and rotation

---

- ◆ Hydraulic pump conditions: Good  

---
- ◆ Engine rotation conditions: Good  

---
- ◆ Engine travel conditions: Good  

---
- ◆ Final drives conditions: Good  

---
- ◆ Hydraulic joint conditions: Good  
Presence of leaks : No  

---
- ◆ Hydraulic joint conditions: Good  
Presence of leaks : No  

---
- ◆ Annotazioni su: Ralla lieve gioco nella norma  

---

### Linkage Group

---

- ◆ Hydraulic conditions linkage group: No  

---
- ◆ Boom structure: Good  
Presence of welding/cracks : No  

---
- ◆ Stick structure: Good  
Presence of welding/cracks : No  

---

- ◆ Flexible pipes conditions: Good  


---
- ◆ Boom cylinders conditions: Good  
Leaks : Yes  


---
- ◆ Stick cylinder conditions: Good  
Leaks : Yes  


---
- ◆ Bucket cylinder conditions: Good  
Leaks : No  


---
- ◆ Pins & Bushings boom conditions: Good  


---
- ◆ Pins & Bushings stick conditions: Good  


---
- ◆ Pins & Bushings bucket conditions: Poor  


---
- ◆ Bucket & Get conditions: Good  


---
- ◆ Quick Coupler conditions: NA - Not applicable  


---
- ◆ Auto Lube working conditions: No  


---

**Cabin and Tools**

---

- ◆ Conditions internal cabin: Good  
Other notes : Sedile da foderare  


---
- ◆ Flashing presents issues: No  


---
- ◆ Lights & Windshield present issues: Not presents  


---
- ◆ Air conditioning is working: Non Presente  


---
- ◆ Back & side camera conditions: Not functioning  


---
- ◆ Annotazioni su: Tergicristallo mancante Vetro anteriore sup Mancante  


---

## Check 81/2008

---

- ◆ Glass conditions: Broken or Chipped - needs repair
- ◆ Lights conditions: Broken or Chipped - needs repair
- ◆ Rear view mirrors conditions: Mancanti
- ◆ Stepladders & handrails conditions: Good
- ◆ Cameras conditions: Broken or Chipped - needs repair
- ◆ Flashing conditions: Not functioning
- ◆ Safety belt conditions: Present and expired
- ◆ Controls been modified: No
- ◆ Presence of Exclusion Control Lever: Yes  
If No, are control levers protected to accidental functionality? : Yes
- ◆ Are Tools Functional & Visible with tag: Yes
- ◆ Canopy completed and comes with keys and bolt: Yes
- ◆ All Pipes with no damage e/o scratches: No
- ◆ Batteries box shielded: Yes
- ◆ Acoustic alarm works properly: No
- ◆ Boardwalk presence: Present and bashee

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.