

SALES REPORT: CATERPILLAR 319C - SN KGL00812 - Year 2007

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: 319C

Family: SMALL EXCAVATOR

Serial Number: KGL00812

Order Number MU/MM: MU00806673

Construction year: 2007

Hour meter: 8364

General residual conditions Truck/Tyres: 35 %

Machine main application: Basic application

Location: Stock Bologna

Rating: ★★☆☆☆

Public price: Ask

MACHINE CONFIGURATION

● Machine type Standard ● Boom type Mono boom ● Boom check valves ● Stick check valves ● Plant features Hammer line ● Bucket Standard Get Teeth ● Truck type Fixed ● General Truck Residual 35% ● Cabin type Fixed standard ● Air Conditioning system ● 21800 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual

MACHINE PHOTOS

◆ Il contaore è:

Funzionante







GENERAL APPEARANCE

◆ Painting Conditions

Poor

◆ Counterweight conditions:

Poor

◆ Frame/Bumper conditions: Poor

TRUCK

◆ Sprockets residual: 35

◆ Front idler wheel residual: 35

◆ Rollers upper/bottom residual: 35

◆ Chains residual: 35

Right side

◆ Door conditions (right): Poor

◆ Spar conditions: Poor

Left side

◆ Door conditions (left): Poor

◆ Door conditions (left): Poor

◆ Spar conditions (left): Poor

◆ Hood/Armor bottom conditions: Present and intact

Functionality

Engine & electrical system functionality

◆ In quale stato è stata visionata la macchina: Accesa e funzionante "al lavoro"

◆ Engine working conditions:	Good
◆ Engine with oil leaks:	No
◆ Engine presents blowby:	No
◆ Oil-Water presence:	No
◆ Engine present smokiness:	No
◆ Radiator conditions:	Good
◆ Starter motor conditions:	Good
◆ Batteries/Cables conditions:	Good
◆ Presence of electrical fault:	Sì

SE SÌ, AGGIUNGERE DETTAGLI : Problema al monitor non si accende

Functionality drive and rotation

◆ Hydraulic pump conditions:	Good
◆ Engine rotation conditions:	Good
◆ Engine travel conditions:	Good
◆ Final drives conditions:	Good
◆ Hydraulic joint conditions:	Good
	Presence of leaks : No
◆ Hydraulic joint conditions:	Good
	Presence of leaks : No

Linkage Group

◆ Hydraulic conditions linkage group:	No
---------------------------------------	----

◆ Boom structure: Good

Presence of welding/cracks : No

◆ Stick structure: Good

Presence of welding/cracks : No

◆ Flexible pipes conditions: Good

◆ Boom cylinders conditions: Good

Leaks : No

◆ Stick cylinder conditions: Good

Leaks : No

◆ Bucket cylinder conditions: Good

Leaks : No

◆ Pins & Bushings boom conditions: Good

◆ Pins & Bushings stick conditions: Good

◆ Pins & Bushings bucket conditions: Good

◆ Bucket & Get conditions: Poor

◆ Quick Coupler conditions: NA - Not applicable

◆ Auto Lube working conditions: No

Cabin and Tools

◆ Conditions internal cabin: Poor

Other notes : Manca vetro frontale

◆ Flashing presents issues: No

◆ Lights & Windshield present issues: Presents and functioning

◆ Air conditioning is working:	Presente e non funzionante
--------------------------------	----------------------------

◆ Back & side camera conditions:	Not functioning
----------------------------------	-----------------

Check 81/2008

◆ Glass conditions:	Broken or Chipped - needs repair
---------------------	----------------------------------

◆ Lights conditions:	Broken or Chipped - needs repair
----------------------	----------------------------------

◆ Rear view mirrors conditions:	Broken or Chipped - needs repair
---------------------------------	----------------------------------

◆ Stepladders & handrails conditions:	Good
---------------------------------------	------

◆ Cameras conditions:	Excellent - no needs repair
-----------------------	-----------------------------

◆ Flashing conditions:	Not functioning
------------------------	-----------------

◆ Safety belt conditions:	Present and expired
---------------------------	---------------------

◆ Controls been modified:	No
---------------------------	----

◆ Presence of Exclusion Control Lever:	Yes
--	-----

◆ Are Tools Functional & Visible with tag:	Yes
--	-----

◆ Canopy completed and comes with keys and bolt:	Yes
--	-----

◆ All Pipes with no damage e/o scratches:	Yes
---	-----

◆ Batteries box shielded:	Yes
---------------------------	-----

◆ Acoustic alarm works properly:	No
----------------------------------	----

◆ Boardwalk presence:	Present and functioning
-----------------------	-------------------------

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.