

SALES REPORT: CASE 695S#KCASE - SN NGHH01727 - Year 2016

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: 695S#KCASE

Family: BACKHOE LOADER

Serial Number: NGHH01727

Order Number MU/MM: MU00807598

Construction year: 2016

Hour meter: 6409

General residual conditions Truck/Tyres: %

Machine main application: Basic application

Location: Stock Off.Buniotto

Rating: ★★☆☆☆

Public price: Ask

MACHINE CONFIGURATION

• Steering type Command steering • Rops Close • Transmission type Hydrostatic • Tyres type undefined • undefined • Ride Control • Bucket Rock/Stone 1.00 1 • Forks a ribaltamento • Differential Type Self-Locking • Auxiliary Systems impianto martello • Bucket Standard 500 mm • Air Conditioning system • 9000 Kg • CE Mark • CE Certificate • Use and maintenance manual • Registration book & Licence plate Registration book & Licence plate

MACHINE PHOTOS





GENERAL APPEARANCE

◆ Painting Conditions:	Good
◆ Frame/Bumper conditions:	Good
◆ Door conditions:	Good
◆ Fender/Mudguard conditions:	Good

Tyres

◆ Front Tyres residual:	50
-------------------------	----

◆ Front Tyres residual: 50

Functionality

Engine & electrical system functionality

◆ In quale stato è stata visionata la macchina: Spenta e ferma

◆ Engine working conditions: Good

◆ Engine with oil leaks: Yes

If Yes, where : copiosa perdita da pistone stabilizzatore sinistro

◆ Engine presents blowby: No

◆ Oil-Water presence: No

◆ Engine present smokiness: No

◆ Radiator conditions: Good

◆ Starter motor conditions: Good

◆ Batteries/Cables conditions: Good

◆ Presence of electrical fault: Non Presente

Functionality drive and rotation

◆ Hydraulic pump conditions: Good

◆ Final drives conditions: Good

◆ Hydraulic joint conditions: Good

Presence of leaks : No

◆ Gear switches go/back conditions: Good

◆ Condizioni snodo centrale (per terna articolata): NA - Non Applicabile

Linkage Group

◆ Hydraulic conditions linkage group: No

◆ Boom structure: Good

Photos

Presence of welding/cracks : No



◆ Flexible pipes conditions: Good

◆ Boom cylinders conditions: Good

Leaks : No

◆ Bucket cylinder conditions: Good

Leaks : No

◆ Pins & Bushings boom conditions: Good

◆ Pins & Bushings bucket conditions: Good

◆ Quick Coupler conditions: NA - Not applicable

◆ Bucket & Get conditions: Poor

◆ Auto Lube working conditions: No

◆ Annotazione sul gruppo caricatore: benna anteriore con salvalama usurati - anche quello della lama 4/1

Linkage Group

◆ Hydraulic conditions linkage group: No

◆ Condizioni snodo / brandeggio braccio: Buono

◆ Boom structure: Good

Photos

Presence of welding/cracks : No



◆ Flexible pipes conditions: Good

◆ Boom cylinders conditions: Good

Leaks : No

◆ Condizioni cilindri avambraccio: Buono

◆ Bucket cylinder conditions: Good

Leaks : No

◆ Pins & Bushings boom conditions: Good

◆ Condizione perni e boccole avambraccio (verifica gioco):	Buono
--	-------

◆ Pins & Bushings bucket conditions:	Poor
--------------------------------------	------

◆ Quick Coupler conditions:	NA - Not applicable
-----------------------------	---------------------

◆ Bucket & Get conditions:	Poor
----------------------------	------

◆ Auto Lube working conditions:	No
---------------------------------	----

Cabin and Tools

◆ Conditions internal cabin:	Good
------------------------------	------

◆ Lights & Windshield present issues:	Presents and functioning
---------------------------------------	--------------------------

◆ Air contidioning & Filters conditions:	Presents and functioning
--	--------------------------

Check 81/2008

◆ Condizioni freni:	Buono
---------------------	-------

◆ Condizioni freno di Stazionamento:	Buono
--------------------------------------	-------

◆ Glass conditions:	Excellent - no needs repair
---------------------	-----------------------------

◆ Lights conditions:	Excellent - no needs repair
----------------------	-----------------------------

◆ Condizioni specchietti:	Eccellente - non necessita riparazione
---------------------------	--

◆ Stepladders & handrails conditions:	Good
---------------------------------------	------

◆ Cameras conditions:	Excellent - no needs repair
-----------------------	-----------------------------

◆ Flashing conditions:	Present and functioning
------------------------	-------------------------

◆ Safety belt conditions:	Present and expired
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	Yes
◆ Boardwalk presence:	Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.