

## SALES REPORT: CATERPILLAR 914 - SN JC300### - Year 2021

This Report is a summary about observations came out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

### MACHINE DATA

---

**Model:** 914

**Family:** SMALL WHEEL LOADER

**Serial Number:** JC300###

**Order Number MU/MM:** MU00810351

**Construction year:** 2021

**Hour meter:** 10318

**General residual conditions Truck/Tyres:** 30 %

**Machine main application:** Industry - corrosive field

**Machine availability date :** 03/02/2026

**Location:** Coming in

**Rating:** ★★☆☆☆

**Public price:** Ask

### MACHINE CONFIGURATION

---

● Machine type Standard - GP ● Steering type Command steering Presence of Command Steering No ● Differential Type Standard ● Transmission type Automatic ● Ride Control . ● Bucket Standard 1.6 MC. Get Cover Blade ● Tyres type Standard ● General Tyres Residual 30 PNEUMATICI MICHELIN 17.5 R25 XHA2 PNEUMATICI MICHELIN 17.5 R25 XHA2 ● Rops Close ● Air Conditioning system ● Auto Lube system ● Product Link ● 8660 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual ● Registration book & Licence plate Registration book & Licence plate ALS487 ●● AVAILABLE FROM MARCH

**MACHINE PHOTOS**

---

◆ Il contaore e':

Funzionante







**GENERAL APPEARANCE**

- ◆ Painting Conditions: Good

---

- ◆ Counterweight conditions: Good

---

- Needs painting? : No

◆ Frame/Bumper conditions:	Good
◆ Door conditions:	Good
◆ Central joint:	Very good
◆ Fender/Mudguard conditions:	Good
◆ Other notes:	TRATTAMENTO ANTICORROSIONE ORIGINALE (- NECESSITA RIVERNICIATURA PARTICOLARI ANTERIORI)

### Tyres

◆ Front Tyres residual:	30
◆ Front Tyres residual:	30

### Functionality

#### Engine & electrical system functionality

◆ In quale stato è stata visionata la macchina:	Accesa e provata per ispezione
◆ Engine working conditions:	Good
◆ Engine with oil leaks:	No
◆ Engine presents blowby:	No
◆ Oil-Water presence:	No
◆ Engine present smokiness:	No
◆ Radiator conditions:	Good
◆ Starter motor conditions:	Good

◆ Batteries/Cables conditions: Good

---

◆ Presence of electrical fault: No

---

### Functionality drive and rotation

---

◆ Hydraulic pump conditions: Good

---

◆ Engine travel conditions: Good

---

◆ Final drives conditions: Good

---

◆ Hydraulic joint conditions: Good

Presence of leaks : No

---

◆ Gear switches go/back conditions: Good

---

### Engine & electrical system functionality

---

◆ Engine working conditions: Good

---

◆ Radiator conditions: Good

---

◆ Starter motor conditions: Good

---

### Linkage Group

---

◆ Tenuta idraulica braccio (il braccio cala): No

---

◆ Boom structure: Good

Presence of welding/cracks : No

---

◆ Flexible pipes conditions: Good

---

◆ Lifting cylinders conditions: Good

---

◆ Bucket cylinder conditions:	Good
◆ Pins & Bushings bucket conditions:	Poor
◆ Bucket & Get conditions:	Poor
◆ Quick Coupler conditions:	NA - Not applicable
◆ Funzionamento Impianto Ingrassaggio Automatico:	Sì

### Cabin and Tools

---

◆ Conditions internal cabin:	Good
◆ Lights & Windshield present issues:	Presents and functioning
◆ Air conditioning & Filters conditions:	Presents and functioning
◆ Back & side camera conditions:	Present and functioning

### Check 81/2008

---

◆ Condizioni freni:	Buono
◆ Condizioni freno di Stazionamento:	Buono
◆ Glass conditions:	Excellent - no needs repair
◆ Lights conditions:	Excellent - no needs repair
◆ Condizioni specchietti:	Eccellente - non necessita riparazione
◆ Stepladders & handrails conditions:	Good
◆ Cameras conditions:	Excellent - no needs repair

◆ Flashing conditions:	Not functioning
◆ Safety belt conditions:	Present and valid
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	Yes
◆ Boardwalk presence:	Not present

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.