

SALES REPORT: VOLVO EC220E - SN 320981 - Year 2016

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: EC220E

Family: MEDIUM EXCAVATOR

Serial Number: 320981

Order Number MU/MM: MU00810505

Construction year: 2016

Hour meter: 11802

General residual conditions Truck/Tyres: 50 %

Machine main application: Basic application

Location: Stock CASERTA

Rating: ★★☆☆☆

Public price: Ask

MACHINE CONFIGURATION


- Machine type Standard
- Boom type Mono boom
- Boom check valves
- Stick check valves
- Plant features Hammer/Crusher line
- Quick coupler Hydraulic volvo
- Bucket Standard 140 Get Teeth
- Truck type Fixed
- General Truck Residual 50%
- Cabin type Fixed standard
- Cabin fog Front superiore
- Air Conditioning system
- 25110 Kg
- CE Mark
- CE Certificate
- Use and maintenance manual

MACHINE PHOTOS

◆ Il contaore è:

Funzionante





◆ Painting Conditions Good

◆ Counterweight conditions: Good

◆ Frame/Bumper conditions: Good

TRUCK

◆ Sprockets residual: 50

◆ Front idler wheel residual: 50

◆ Rollers upper/bottom residual: 50

◆ Chains residual: 50

Right side

◆ Door conditions (right): Good

◆ Spar conditions: Good

Left side

◆ Door conditions (left): Good

◆ Door conditions (left): Good

◆ Spar conditions (left): Good

◆ Hood/Armor bottom conditions: Present and intact

Functionality

Engine & electrical system functionality

- ◆ In quale stato è stata visionata la macchina: Accesa e provata per ispezione

- ◆ Engine working conditions: Good

- ◆ Engine with oil leaks: No

- ◆ Engine presents blowby: No

- ◆ Oil-Water presence: No

- ◆ Engine present smokiness: No

- ◆ Radiator conditions: Good

- ◆ Starter motor conditions: Good

- ◆ Batteries/Cables conditions: Good

- ◆ Presence of electrical fault: No

Functionality drive and rotation

- ◆ Hydraulic pump conditions: Good

- ◆ Engine rotation conditions: Good

- ◆ Engine travel conditions: Good

- ◆ Final drives conditions: Good

- ◆ Hydraulic joint conditions: Good
Presence of leaks : No

- ◆ Hydraulic joint conditions: Good
Presence of leaks : No

Linkage Group

◆ Hydraulic conditions linkage group:	No
<hr/>	
◆ Boom structure:	Good
	Presence of welding/cracks : No
<hr/>	
◆ Stick structure:	Good
	Presence of welding/cracks : No
<hr/>	
◆ Flexible pipes conditions:	Good
<hr/>	
◆ Boom cylinders conditions:	Good
	Leaks : No
<hr/>	
◆ Stick cylinder conditions:	Good
	Leaks : No
<hr/>	
◆ Bucket cylinder conditions:	Good
	Leaks : No
<hr/>	
◆ Pins & Bushings boom conditions:	Poor
<hr/>	
◆ Pins & Bushings stick conditions:	Poor
<hr/>	
◆ Pins & Bushings bucket conditions:	Poor
<hr/>	
◆ Bucket & Get conditions:	Poor
<hr/>	
◆ Quick Coupler conditions:	Good
<hr/>	
◆ Auto Lube working conditions:	No
<hr/>	

Cabin and Tools

◆ Conditions internal cabin:	Good
<hr/>	

- ◆ Flashing presents issues: No

- ◆ Lights & Windshield present issues: Presents and functioning

- ◆ Air conditioning is working: Presente e funzionante

- ◆ Back & side camera conditions: Not functioning

Check 81/2008

- ◆ Glass conditions: Excellent - no needs repair

- ◆ Lights conditions: Excellent - no needs repair

- ◆ Rear view mirrors conditions: Excellent - no needs repair

- ◆ Stepladders & handrails conditions: Good

- ◆ Cameras conditions: Excellent - no needs repair

- ◆ Flashing conditions: Not functioning

- ◆ Safety belt conditions: Present and expired

- ◆ Controls been modified: No

- ◆ Presence of Exclusion Control Lever: Yes

- If No, are control levers protected to accidental functionality? : Yes

- ◆ Are Tools Functional & Visible with tag: Yes

- ◆ Canopy completed and comes with keys and bolt: Yes

- ◆ All Pipes with no damage e/o scratches: Yes

- ◆ Batteries box shielded: Yes

- ◆ Acustic alarm works properly: Yes

◆ Boardwalk presence:

Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.