

SALES REPORT: MANITOU MRT 1845 - SN MAN00000P01076### - Year 2022

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: MRT 1845

Family: FIXED TELESCOPIC HANDLER

Serial Number: MAN00000P01076###

Order Number MU/MM: MU00811678

Construction year: 2022

Hour meter: 240

General residual conditions Truck/Tyres: 90 %

Machine main application: Basic application, Industry - not corrosive field

Machine availability date : 27/02/2026

Location: Coming in

Rating: ★★★★★

Public price: 145.000 €

MACHINE CONFIGURATION

• Machine type HLA • Boom type Mono boom • Boom check valves • undefined • Tyres type undefined • Stabilizers 4 Stabilizers • Auxiliary Systems • Quick Coupler System • Bucket Standard Get Cover Blade • Forks • Saddle attachment • CE Certificate • Tyres type Standard • General Tyres Residual 90 • Rops Close • Antitheft alarm • 138000 Kg • • CE Mark • CE Certificate • EPA Tag • Use and maintenance manual • Registration book & Licence plate Registration book & Licence plate

MACHINE PHOTOS

◆ Il contaore e':

Funzionante







GENERAL APPEARANCE

Painting Conditions:	Very Good
Counterweight conditions:	Good
	Needs painting? : No
Frame/Bumper conditions:	Good
Door conditions:	Very good
Fender/Mudguard conditions:	Very good

Tyres

Front Tyres residual:	90
Front Tyres residual:	90

Functionality

Engine & electrical system functionality

◆ In quale stato è stata visionata la macchina:	Accesa e funzionante "al lavoro"
◆ Engine working conditions:	Very good
◆ Engine with oil leaks:	No
◆ Engine presents blowby:	No
◆ Oil-Water presence:	No
◆ Engine present smokiness:	No
◆ Radiator conditions:	Very good
◆ Starter motor conditions:	Very good
◆ Batteries/Cables conditions:	Very good
◆ Presence of electrical fault:	No

Functionality drive and rotation

◆ Hydraulic pump conditions:	Very good
◆ Engine travel conditions:	Very good
◆ Final drives conditions:	Very good
◆ Hydraulic joint conditions:	Very good
	Presence of leaks : No
◆ Gear switches go/back conditions:	Very Good

Engine & electrical system functionality

◆ Engine working conditions: Very good

◆ Radiator conditions: Very good

Linkage Group

◆ Tenuta idraulica braccio (il braccio cala): No

◆ Boom structure: Very good

Photos

Presence of welding/cracks : No

FOTO IN AGGIORNAMENTO



FOTO IN AGGIORNAMENTO



◆ Flexible pipes conditions: Very good

◆ Lifting cylinders conditions: Very good

◆ Bucket cylinder conditions: Very good

◆ Pins & Bushings bucket conditions: Very good

◆ Bucket & Get conditions: Good

◆ Quick Coupler conditions: Good

◆ Funzionamento Impianto Ingrassaggio Automatico: No

Cabin and Tools

◆ Conditions internal cabin:	Good
Other notes : Display con appannati	
◆ Lights & Windshield present issues:	Presents and functioning
◆ Air contidioning & Filters conditions:	Presents and functioning
◆ Back & side camera conditions:	Present and functioning

Check 81/2008

◆ Condizioni freni:	Molto Buono
◆ Condizioni freno di Stazionamento:	Molto Buono
◆ Glass conditions:	Excellent - no needs repair
◆ Lights conditions:	Excellent - no needs repair
◆ Condizioni specchietti:	Eccellente - non necessita riparazione
◆ Stepladders & handrails conditions:	Very good
◆ Cameras conditions:	Excellent - no needs repair
◆ Flashing conditions:	Present and functioning
◆ Safety belt conditions:	Present and valid
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes

If No, are control levers protected to accidental funcionality? : Yes

◆ Are Tools Functional & Visible with tag:	No
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	Yes
◆ Boardwalk presence:	Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.

Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.

Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".

Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo.

Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues.

Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.

Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.

No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".

Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one.

Main components-with 70/80% of life residue. Machine in security conditions.