

SALES REPORT: KOMATSU PC350#KKOMA - SN K50448 - Year 2008

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: PC350#KKOMA

Family: MEDIUM EXCAVATOR

Serial Number: K50448

Order Number MU/MM: MU00812001

Construction year: 2008

Hour meter: 11135

General residual conditions Truck/Tyres: 60 %

Machine main application: Heavy application

Location: Stock Milano Usato

Rating: ★★☆☆☆

Public price: Ask

MACHINE CONFIGURATION

● Machine type Standard ● Boom type Triple boom ● Boom check valves ● Stick check valves ● Plant features Versatility impianto dedicato all'attacco rapido linea drenaggio ● Quick coupler Hydraulic tipo Liebherr ● Bucket Standard 1700 /1600 Get Teeth ● Truck type Fixed ● General Truck Residual 60% carro con catene allungate dall'usura interna tra perni e boccole Esternamente si presenta bene ● Cabin type Fixed standard ● Cabin fog Front ● Air Conditioning system ● Auto Lube system ● Product Link ● 34300 Kg ● CE Mark ● CE Certificate ● EPA Tag ● Use and maintenance manual

MACHINE PHOTOS

◆ Il contaore è:

Funzionante







GENERAL APPEARANCE

◆ Painting Conditions Poor

◆ Counterweight conditions: Poor

◆ Frame/Bumper conditions: Good

TRUCK

◆ Sprockets residual: 70

◆ Front idler wheel residual: 70

◆ Rollers upper/bottom residual: 60

◆ Chains residual: 60

◆ Altre anomalie catene allungate per usura interna tra perni e boccole

Right side

◆ Door conditions (right): Poor

◆ Spar conditions: Good

◆ Other issues: sportello posteriore destro ammaccato

Left side

◆ Door conditions (left): Good

◆ Door conditions (left): Good

◆ Spar conditions (left): Good

◆ Hood/Armor bottom conditions: Present and intact

Functionality

Engine & electrical system functionality

- ◆ In quale stato è stata visionata la macchina: Accesa e provata per ispezione

 - ◆ Engine working conditions: Good

 - ◆ Engine with oil leaks: No

 - ◆ Engine presents blowby: No

 - ◆ Oil-Water presence: No

 - ◆ Engine present smokiness: No

 - ◆ Radiator conditions: Poor

 - ◆ Starter motor conditions: Good

 - ◆ Batteries/Cables conditions: Good

 - ◆ Presence of electrical fault: No

 - ◆ Annotazioni su radiatore after cooler bucato tappato con silicone come da foto Da sostituire
-

Functionality drive and rotation

- ◆ Hydraulic pump conditions: Good

- ◆ Engine rotation conditions: Good

- ◆ Engine travel conditions: Good

- ◆ Final drives conditions: Good

- ◆ Hydraulic joint conditions: Good

Presence of leaks : No

◆ Hydraulic joint conditions: Poor

Presence of leaks : No

◆ Annotazioni su:
giunto rotante con sfuggita di olio da revisionare cingolo di sinistra fa fatica a traslare , va a colpi ma non si sentono rumori meccanici pompa idraulica dei servocomandi da controllare perche i movimenti sono ritardati rispetto ai comandi dati

Linkage Group

◆ Hydraulic conditions linkage group: No

◆ Boom structure: Good

Presence of welding/cracks : No

◆ Stick structure: Good

Presence of welding/cracks : No

◆ Flexible pipes conditions: Good

◆ Boom cylinders conditions: Good

Leaks : No

◆ Stick cylinder conditions: Good

Leaks : No

◆ Bucket cylinder conditions: Good

Leaks : No

◆ Pins & Bushings boom conditions: Poor

◆ Pins & Bushings stick conditions: Poor

◆ Pins & Bushings bucket conditions: Poor

◆ Bucket & Get conditions: Good

◆ Quick Coupler conditions: Good

◆ Auto Lube working conditions: No

◆ Annotazione sul gruppo caricatore: perdite di olio dai tubi idraulici sul primo braccio

Cabin and Tools

◆ Conditions internal cabin: Good

◆ Flashing presents issues: No

◆ Lights & Windshield present issues: Presents and functioning

◆ Air conditioning is working: Presente e funzionante

◆ Back & side camera conditions: Present and not functioning

Check 81/2008

◆ Glass conditions: Excellent - no needs repair

◆ Lights conditions: Excellent - no needs repair

◆ Rear view mirrors conditions: Excellent - no needs repair

◆ Stepladders & handrails conditions: Good

◆ Cameras conditions: Broken or Chipped - needs repair

◆ Flashing conditions: Present and not functioning

◆ Safety belt conditions: Present and expired

◆ Controls been modified: No

◆ Presence of Exclusion Control Lever: Yes

If No, are control levers protected to accidental functionality? : No

◆ Are Tools Functional & Visible with tag: Yes

◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	No
◆ Boardwalk presence:	Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.