

## SALES REPORT: CATERPILLAR 306 CR - SN 6W600### - Year 2022

This Report is a summary about observations came out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

### MACHINE DATA

---

**Model:** 306 CR

**Family:** MINI EXCAVATOR

**Serial Number:** 6W600###

**Order Number MU/MM:** MU00812587

**Construction year:** 2022

**Hour meter:** 2069

**General residual conditions Truck/Tyres:** 70 %

**Machine main application:** Basic application

**Machine availability date :** 11/03/2026

**Location:** Coming in

**Rating:** ★★☆☆☆

**Public price:** Ask

### MACHINE CONFIGURATION

---

- Machine type Standard
- Boom type Mono boom
- Boom check valves
- Stick check valves
- Plant features Versatility
- Quick coupler Mechanic Cr50
- Bucket Standard
- Truck type Fixed
- Blade
- General Truck Residual 10%
- Cabin type Fixed standard
- Air Conditioning system
- Product Link
- Antitheft alarm
- 6000 Kg
- CE Mark
- CE Certificate
- EPA Tag
- Use and maintenance manual

**MACHINE PHOTOS**

---

◆ Il contaore è:

Funzionante







**GENERAL APPEARANCE**

---

◆ Painting Conditions	Good
<hr/>	
◆ Counterweight conditions:	Poor
<hr/>	
◆ Frame/Bumper conditions:	Good

**TRUCK**

---

◆ Sprockets residual:	70
<hr/>	
◆ Front idler wheel residual:	70
<hr/>	
◆ Rollers upper/bottom residual:	70
<hr/>	
◆ Chains residual:	50

**Right side**

---

◆ Door conditions (right):	Good
<hr/>	
◆ Spar conditions:	Good

---

### Left side

---

- ◆ Door conditions (left): Good

---

- ◆ Door conditions (left): Good

---

- ◆ Spar conditions (left): Good

---

- ◆ Hood/Armor bottom conditions: Present and intact

---

### Functionality

---

#### Engine & electrical system functionality

---

- ◆ In quale stato è stata visionata la macchina: Accesa e provata per ispezione

---

- ◆ Engine working conditions: Good

---

- ◆ Engine with oil leaks: No

---

- ◆ Engine presents blowby: No

---

- ◆ Oil-Water presence: Yes

---

- ◆ Engine present smokiness: No

---

- ◆ Radiator conditions: Good

---

- ◆ Starter motor conditions: Good

---

- ◆ Batteries/Cables conditions: Good

---

- ◆ Presence of electrical fault: No

---

### Functionality drive and rotation

---

- ◆ Hydraulic pump conditions: Good

---

- ◆ Engine rotation conditions: Good

---

- ◆ Engine travel conditions: Good

---

- ◆ Final drives conditions: Good

---

- ◆ Hydraulic joint conditions: Good  
Presence of leaks : No

---

- ◆ Hydraulic joint conditions: Good  
Presence of leaks : No

---

### Linkage Group

---

- ◆ Hydraulic conditions linkage group: No

---

- ◆ Boom structure: Good  
Presence of welding/cracks : No

---

- ◆ Stick structure: Good  
Presence of welding/cracks : No

---

- ◆ Flexible pipes conditions: Good

---

- ◆ Boom cylinders conditions: Good  
Leaks : No

---

- ◆ Stick cylinder conditions: Good  
Leaks : No

---

- ◆ Bucket cylinder conditions: Good  
Leaks : No

---

- ◆ Pins & Bushings boom conditions: Good

- 
- ◆ Pins & Bushings stick conditions: Good

---

  - ◆ Pins & Bushings bucket conditions: Good

---

  - ◆ Bucket & Get conditions: Good

---

  - ◆ Quick Coupler conditions: Good

---

  - ◆ Auto Lube working conditions: No
- 

### Cabin and Tools

---

- ◆ Conditions internal cabin: Good

---

  - ◆ Flashing presents issues: No

---

  - ◆ Lights & Windshield present issues: Presents and functioning

---

  - ◆ Air conditioning is working: Presente e funzionante

---

  - ◆ Back & side camera conditions: Present and functioning
- 

### Check 81/2008

---

- ◆ Glass conditions: Excellent - no needs repair

---

  - ◆ Lights conditions: Excellent - no needs repair

---

  - ◆ Rear view mirrors conditions: Broken or Chipped - needs repair

---

  - ◆ Stepladders & handrails conditions: Poor

---

  - ◆ Cameras conditions: Excellent - no needs repair

---

  - ◆ Flashing conditions: Not functioning
-

◆ Safety belt conditions:	Present and valid
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	No
	If No, are control levers protected to accidental functionality? : No
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	No
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	Yes
◆ Boardwalk presence:	Present and functioning

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.