

SALES REPORT: CATERPILLAR MH3022 - SN FM200### - Year 2015

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: MH3022

Family: WHEEL EXCAVATOR

Serial Number: FM200###

Order Number MU/MM: MU00813048

Construction year: 2015

Hour meter: 11533

General residual conditions Truck/Tyres: 70 %

Machine main application: Industry - corrosive field

Machine availability date : 06/02/2026

Location: Coming in

Rating: ★★☆☆☆

Public price: Ask


MACHINE CONFIGURATION

• Machine type Standard material handling mh • Boom type Mono boom • Boom check valves • Stick check valves • Plant features Versatility Macchina da ritirare senza polipo. Avambraccio da scavo con leverismo benna ed attacco benna smontati nuovi, da permutare anche quelli. • Tyres type Twin Wheel • General Tyres Residual 70 10.00 20 Globe star • Stabilizers 4 Stabilizers • Cabin type Hydraulic lift • Cabin fog Front superiore • Air Conditioning system Operation Yes • Auto lube system Operation Yes • Product Link • Antitheft alarm • 23000 Kg • CE Mark • CE Certificate • EPA Tag • Use and maintenance manual • Registration book & Licence plate No Registration book & Licence plate • AVAILABLE FROM APRIL


MACHINE PHOTOS



◆ Il contaore e':

Funzionante









GENERAL APPEARANCE

◆ Painting Conditions	Very Good
◆ Counterweight conditions	Very good
	Needs painting? : No
◆ Frame / Bumper conditions	Very Good

Tyres

◆ Front Tyres residual	70
◆ Front Tyres residual	70

Right side

◆ Door conditions (right)	Very good
◆ Spar conditions (right)	Very good

Left side

◆ Door conditions (left)	Excellent
◆ Door conditions (left)	Excellent
◆ Spar conditions (left)	Very good
◆ Hood / Armor bottom conditions	Present and intact

Functionality

Engine & electrical system functionality

◆ In quale stato è stata visionata la macchina:	Accesa e funzionante "al lavoro"
◆ Engine functionality conditions	Very good
◆ Engine with oil leaks	No
◆ Engine presents blowby	No

◆ Oil-Water presence	No
◆ Engine present smokiness	No
◆ Radiator conditions	Excellent
◆ Starter motor conditions	Very good
◆ Batteries/Cables conditions	Very good
◆ Presence of electrical fault	Sì

If present, add details : Rotazione polipo non funzionante. Fatto sopralluogo, è un problema elettrico. Da capire la causa.

Functionality drive and rotation

◆ Hydraulic pump conditions	Very good
◆ Engine rotation conditions	Very good
◆ Engine travel conditions	Very good
◆ Final drives conditions	Very good
◆ Hydraulic joint conditions	Very good
	Presence of leaks : No
◆ Hydraulic joint conditions	Very good
	Presence of leaks : No
◆ Tenuta idraulica braccio (il braccio cala):	No

Linkage Group

◆ Hydraulic conditions linkage group (Boom is lowering?)	Yes
◆ Boom structure	Very good

Presence of welding/cracks : No

◆ Stick structure	Very good
	Presence of welding/cracks : No
◆ Flexible pipes conditions	Very good
◆ Boom cylinders conditions	Very good
	Leaks : No
◆ Stick cylinder conditions	Very good
	Leaks : No
◆ Bucket / Grapple cylinder conditions	Excellent
	Leaks : No
◆ Pins & Bushings boom conditions	Very good
◆ Pins & Bushings stick conditions	Very good
◆ Pins & Bushings bucket conditions	Very good
◆ Bucket / Grapple & Get conditions	Good
◆ Quick Coupler conditions	NA - Not applicable
◆ Funzionamento Impianto Ingrassaggio Automatico:	Sì

Cabin and Tools

◆ Conditions internal cabin	Excellent
◆ Flashing presents issues	No
◆ Lights & Windshield present issues	Presents and functioning
◆ Air conditioning & Filters conditions	Presents and functioning
◆ Back & side camera conditions	Present and functioning

Check 81/2008

◆ Condizioni freni:	Molto Buono
◆ Condizioni freno di Stazionamento:	Molto Buono
◆ Glass conditions	Excellent - no needs repair
◆ Lights conditions	Excellent - no needs repair
◆ Rear view mirrors conditions	Excellent - no needs repair
◆ Stepladders & handrails conditions	Very good
◆ Cameras conditions	Excellent - no needs repair
◆ Flashing conditions	Not functioning
◆ Safety belt conditions	Present and valid
◆ Controls been modified	No
◆ Presence of Exclusion Control Lever	Yes
◆ Are Tools Functional & Visible with tag	Yes
◆ Canopy completed and comes with keys and bolt	Yes
◆ All Pipes with no damage e/o scratches	Yes
◆ Batteries box shielded	Yes
◆ Acoustic alarm works properly	Yes
◆ Boardwalk presence	Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.