

## SALES REPORT: ALTRE MARCHE RTH6.25 - SN 00003### - Year 2020

This Report is a summary about observations came out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

### MACHINE DATA

---

**Model:** RTH6.25

**Family:** FIXED TELESCOPIC HANDLER

**Serial Number:** 00003###

**Order Number MU/MM:** MU00813535

**Construction year:** 2020

**Hour meter:** 1314

**General residual conditions Truck/Tyres:** 70 %

**Machine main application:** Basic application

**Machine availability date :** 25/02/2025

**Location:** Coming in

**Rating:** ★★☆☆☆

**Public price:** Ask

### MACHINE CONFIGURATION


---

● Machine type HLA ● Boom type Triple boom ● Boom check valves ● undefined ● Tyres type undefined ● Stabilizers 4 Stabilizers ● Auxiliary Systems ● Quick coupler Mechanic Magni ● Bucket Standard NO BENNA BENNA NON PRESENTE, MAI ACQUISTATA DAL CLIENTE ● Forks ● Saddle attachment ● CE Certificate ● Tyres type Standard ● General Tyres Residual 70 445/65 R22.5 Magni Ho dovuto fleggare BENNA Std, MA LA BENNA NON E'PRESENTE ● Rops Close ● Air Conditioning system ● 17980 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual ● Registration book & Licence plate Registration book & Licence plate AKA544

**MACHINE PHOTOS**

---







**GENERAL APPEARANCE**

---

- ◆ Painting Conditions: Good

---

- ◆ Counterweight conditions: Good

Needs painting? : No

---

- ◆ Frame/Bumper conditions: Good

---

- ◆ Door conditions: Good

---

- ◆ Fender/Mudguard conditions: Good

---

**Tyres**

---

- ◆ Front Tyres residual: 70

---

- ◆ Front Tyres residual: 70

---

## Functionality

---

### Engine & electrical system functionality

---

◆ In quale stato è stata visionata la macchina:	Accesa e provata per ispezione
◆ Engine working conditions:	Good
◆ Engine with oil leaks:	No
◆ Engine presents blowby:	No
◆ Oil-Water presence:	No
◆ Engine present smokiness:	No
◆ Radiator conditions:	Good
◆ Starter motor conditions:	Good
◆ Batteries/Cables conditions:	Good
◆ Presence of electrical fault:	No

### Functionality drive and rotation

---

◆ Hydraulic pump conditions:	Good
◆ Engine travel conditions:	Good
◆ Final drives conditions:	Good
◆ Hydraulic joint conditions:	NA - Not applicable
	Presence of leaks : No
◆ Gear switches go/back conditions:	Good

---

### Engine & electrical system functionality

---

- ◆ Engine working conditions: Good

---

- ◆ Radiator conditions: Good

---

### Linkage Group

---

- ◆ Tenuta idraulica braccio (il braccio cala): No

---

- ◆ Boom structure: Good

Photos

Presence of welding/cracks : No



- 
- ◆ Flexible pipes conditions: Good

---

  - ◆ Lifting cylinders conditions: Good

---

  - ◆ Bucket cylinder conditions: Good

---

- ◆ Pins & Bushings bucket conditions: Good

---

- ◆ Bucket & Get conditions: Good

---

- ◆ Quick Coupler conditions: Good

---

- ◆ Funzionamento Impianto Ingrassaggio Automatico: No

---

## Cabin and Tools

---

- ◆ Conditions internal cabin: Good

---

- ◆ Lights & Windshield present issues: Presents and functioning

---

- ◆ Air conditioning & Filters conditions: Presents and functioning

---

- ◆ Back & side camera conditions: Not functioning

---

## Check 81/2008

---

- ◆ Condizioni freni: Buono

---

- ◆ Condizioni freno di Stazionamento: Buono

---

- ◆ Glass conditions: Excellent - no needs repair

---

- ◆ Lights conditions: Excellent - no needs repair

---

- ◆ Condizioni specchietti: Eccellente - non necessita riparazione

---

- ◆ Stepladders & handrails conditions: Good

---

- ◆ Cameras conditions: Excellent - no needs repair

---

- ◆ Flashing conditions: Present and functioning

---

◆ Safety belt conditions:	Present and expired
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	Yes
◆ Boardwalk presence:	Present and functioning

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.