

**SALES REPORT: CASE 321F#KCASE - SN FNH321FHNNHP04### - Year 2022**

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

**GENERAL CONDITIONS**

---

**MACHINE DATA**

---

**Model:** 321F#KCASE

**Family:** COMPACT WHEEL LOADER

**Serial Number:** FNH321FHNNHP04###

**Order Number MU/MM:** MU00813671

**Construction year:** 2022

**Hour meter:** 2467

**General residual conditions Truck/Tyres:** 50 %

**Machine main application:** Basic application

**Machine availability date :** 27/02/2026

**Location:** Coming in

**Rating:** ★★☆☆☆

**Public price:** Ask

**MACHINE CONFIGURATION**

---

- Machine type Standard - GP • Steering type Command steering Presence of Command Steering No • Differential Type Controlled Slippage • Transmission type Hydrostatic • Auxiliary Systems • Quick Coupler System • Quick coupler Hydraulic Case • Bucket Standard 0,8m3 Get Cover Blade • Forks • Tyres type Standard • General Tyres Residual 50 405/70 R20 Alliance • Rops Close • 6100 Kg • CE Mark • CE Certificate • Registration book & Licence plate Registration book & Licence plate AKA570 • AVAILABLE FROM APRIL

**MACHINE PHOTOS**

---







◆ Front Tyres residual: 50

---

◆ Front Tyres residual: 50

---

## Functionality

---

### Engine & electrical system functionality

---

◆ In quale stato è stata visionata la macchina: Accesa e funzionante "al lavoro"

---

◆ Engine working conditions: Very good

---

◆ Engine with oil leaks: No

---

◆ Engine presents blowby: No

---

◆ Oil-Water presence: No

---

◆ Engine present smokiness: No

---

◆ Radiator conditions: Very good

---

◆ Starter motor conditions: Good

---

◆ Batteries/Cables conditions: Good

---

◆ Presence of electrical fault: No

---

### Functionality drive and rotation

---

◆ Hydraulic pump conditions: Good

---

◆ Engine travel conditions: Very good

---

◆ Final drives conditions: Very good

---

◆ Hydraulic joint conditions: NA - Not applicable

Presence of leaks : No

---

◆ Gear switches go/back conditions: Very Good

---

### Engine & electrical system functionality

---

◆ Engine working conditions: Very good

---

◆ Radiator conditions: Very good

---

◆ Starter motor conditions: Very good

---

### Linkage Group

---

◆ Tenuta idraulica braccio (il braccio cala): No

---

◆ Boom structure: Very good

Presence of welding/cracks : No

---

◆ Flexible pipes conditions: Very good

---

◆ Lifting cylinders conditions: Very good

---

◆ Bucket cylinder conditions: Very good

---

◆ Pins & Bushings bucket conditions: Good

---

◆ Bucket & Get conditions: Good

---

◆ Quick Coupler conditions: Good

---

◆ Funzionamento Impianto Ingrassaggio Automatico: No

---

### Cabin and Tools

---

◆ Conditions internal cabin:	Good
◆ Lights & Windshield present issues:	Presents and functioning
◆ Air contidioning & Filters conditions:	Not functioning
◆ Back & side camera conditions:	Not functioning

### Check 81/2008

◆ Condizioni freni:	Molto Buono
◆ Condizioni freno di Stazionamento:	Molto Buono
◆ Glass conditions:	Excellent - no needs repair
◆ Lights conditions:	Excellent - no needs repair
◆ Condizioni specchietti:	Eccellente - non necessita riparazione
◆ Stepladders & handrails conditions:	Very good
◆ Cameras conditions:	Broken or Chipped - needs repair
◆ Flashing conditions:	Present and functioning
◆ Safety belt conditions:	Present and valid
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes

---

◆ Acoustic alarm works properly: Yes

---

◆ Boardwalk presence: Not present

---

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.