

## SALES REPORT: VOLVO L90G - SN VCE0L90GL00003451 - Year 2012

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

### MACHINE DATA

---

**Model:** L90G

**Family:** MEDIUM WHEEL LOADER

**Serial Number:** VCE0L90GL00003451

**Order Number MU/MM:** MU00814176

**Construction year:** 2012

**Hour meter:** 10160

**General residual conditions Truck/Tyres:** 80 %

**Machine main application:** Industry - not corrosive field

**Location:** Stock Milano Usato

**Rating:** ★★☆☆☆

**Public price:** Ask

### MACHINE CONFIGURATION

---

• Machine type Standard - GP • Steering type Command steering • Differential Type Standard • Transmission type Automatic • Ride Control • Quick Coupler System • Bucket Standard - Get Cover Blade • Tyres type Rock • General Tyres Residual 80 20.5R25 • • Rops Close • Air Conditioning system • 17300 Kg • CE Mark • CE Certificate • Use and maintenance manual • Registration book & Licence plate undefined

**MACHINE PHOTOS**

---

◆ Il contaore e':

Funzionante





## GENERAL APPEARANCE

---

◆ Painting Conditions:	Good
◆ Counterweight conditions:	Good
	Needs painting? : No
◆ Frame/Bumper conditions:	Good
◆ Door conditions:	Good
◆ Central joint:	Good
◆ Fender/Mudguard conditions:	Good

## Tyres

---

◆ Front Tyres residual:	80
◆ Front Tyres residual:	80

## Functionality

---

### Engine & electrical system functionality

---

◆ In quale stato è stata visionata la macchina:	Spenta e ferma
◆ Engine working conditions:	Good
◆ Engine with oil leaks:	No
◆ Engine presents blowby:	No
◆ Oil-Water presence:	No
◆ Engine present smokiness:	No
◆ Radiator conditions:	Good
◆ Starter motor conditions:	Good
◆ Batteries/Cables conditions:	Good
◆ Presence of electrical fault:	No

---

### Functionality drive and rotation

---

◆ Hydraulic pump conditions:	Good
◆ Engine travel conditions:	NA - Not applicable
◆ Final drives conditions:	Good
◆ Hydraulic joint conditions:	Good
	Presence of leaks : No
◆ Gear switches go/back conditions:	Good

---

### Engine & electrical system functionality

---

◆ Engine working conditions:	Good
------------------------------	------

---

◆ Radiator conditions: Good

---

◆ Starter motor conditions: Good

---

### Linkage Group

---

◆ Tenuta idraulica braccio (il braccio cala): No

---

◆ Boom structure: Good

Presence of welding/cracks : No

---

◆ Flexible pipes conditions: Good

---

◆ Lifting cylinders conditions: Good

---

◆ Bucket cylinder conditions: Good

---

◆ Pins & Bushings bucket conditions: Good

---

◆ Bucket & Get conditions: Good

---

◆ Quick Coupler conditions: NA - Not applicable

---

◆ Funzionamento Impianto Ingrassaggio Automatico: No

---

### Cabin and Tools

---

◆ Conditions internal cabin: Good

---

◆ Lights & Windshield present issues: Present and not functioning

---

◆ Air conditioning & Filters conditions: Presents and functioning

---

◆ Back & side camera conditions: Present and functioning

---

**Check 81/2008**

---

◆ Condizioni freni:	Buono
◆ Condizioni freno di Stazionamento:	Buono
◆ Glass conditions:	Excellent - no needs repair
◆ Lights conditions:	Excellent - no needs repair
◆ Condizioni specchietti:	Eccellente - non necessita riparazione
◆ Stepladders & handrails conditions:	Good
◆ Cameras conditions:	Excellent - no needs repair
◆ Flashing conditions:	Present and functioning
◆ Safety belt conditions:	Present and expired
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	Yes
◆ Boardwalk presence:	Not present

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.