

SALES REPORT: BITELLI SF200L - SN 970033 - Year 1997

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: SF200L

Family: COLD PLANER

Serial Number: 970033

Order Number MU/MM: MU00814698

Construction year: 1997

Hour meter: 7016

General residual conditions Truck/Tyres: %

Machine main application:

Location: In comodato


Rating: ★★☆☆☆



MACHINE CONFIGURATION

● Machine type Standard ● Boom type ● Plant features ● Truck type 20 ● Product Link 70 ● EPA Tag 70 ● 50 ● 28700 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual

MACHINE PHOTOS









GENERAL APPEARANCE

◆ Painting Conditions

Good

◆ Spar conditions:

Good

Functionality

Engine & electrical system functionality

- ◆ In quale stato è stata visionata la macchina: Accesa e provata per ispezione

- ◆ Engine working conditions: Good

- ◆ Engine with oil leaks: Yes
If Yes, where : Trasudi testata motore

- ◆ Engine presents blowby: No

- ◆ Engine present smokiness: No

- ◆ Radiator conditions: Poor

- ◆ Starter motor conditions: Good

- ◆ Batteries/Cables conditions: Good

- ◆ Presence of electrical fault: No

Functionality drive and rotation

- ◆ Hydraulic pump conditions: Good

- ◆ Engine travel conditions: Good

- ◆ Final drives conditions: Good

- ◆ Hydraulic joint conditions: Good

- ◆ Door conditions (left): Good

- ◆ Door conditions (left): Good

Inserire Misura (mm.) : 2000

Linkage Group

- ◆ Boom structure: Very good
 Presenza di perdite? Se si, specificare da dove: : Si pistone colonnina anteriore si

- ◆ Stick structure: Good
 Presenza di perdite? Se si, specificare da dove: : Posteriore sx

- ◆ Flexible pipes conditions: Good
 Presenza di perdite? Se si, specificare da dove: : Buono

- ◆ Boom cylinders conditions: Good

Check 81/2008

- ◆ Lights conditions: Excellent - no needs repair

- ◆ Condizioni specchietti: Rotto o Scheggiato - necessita riparazione

- ◆ Stepladders & handrails conditions: Good

- ◆ Cameras conditions: Excellent - no needs repair

- ◆ Flashing conditions: Present and functioning

- ◆ Controls been modified: No

- ◆ Presence of Exclusion Control Lever: Yes
 If No, are control levers protected to accidental funcionality? : Yes

- ◆ Are Tools Functional & Visible with tag: Yes

- ◆ Canopy completed and comes with keys and bolt: Yes

- ◆ All Pipes with no damage e/o scratches: Yes

- ◆ Batteries box shielded: Yes

◆ Acoustic alarm works properly: Yes

◆ Boardwalk presence: Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.