

SALES REPORT: VOLVO L260H - SN VCEL260HA00002### - Year 2024

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: L260H

Family: MEDIUM WHEEL LOADER

Serial Number: VCEL260HA00002###

Order Number MU/MM: MU00814718

Construction year: 2024

Hour meter: 1879

General residual conditions Truck/Tyres: 80 %

Machine main application: Basic application

Machine availability date : 27/03/2026

Location: Coming in

Rating: ★★★★★

Public price: 640.000 €

MACHINE CONFIGURATION

• Machine type Standard - GP • Steering type Command steering Presence of Command Steering Yes • Differential Type Controlled Slippage • Transmission type Automatic • Ride Control • Bucket Standard Get Cover Blade • Tyres type Standard • General Tyres Residual 80 MICHELIN • Rops Close • Air Conditioning system • Weight Scale • 39000 Kg • CE Mark • CE Certificate • Use and maintenance manual • Registration book & Licence plate undefined

MACHINE PHOTOS

◆ Il contaore e':

Funzionante





GENERAL APPEARANCE

◆ Painting Conditions:	Very Good
<hr/>	
◆ Counterweight conditions:	Very good
	Needs painting? : No
<hr/>	
◆ Frame/Bumper conditions:	Very Good
<hr/>	
◆ Door conditions:	Very good
<hr/>	
◆ Central joint:	Very good
<hr/>	
◆ Fender/Mudguard conditions:	Very good

Tyres

◆ Front Tyres residual:	79
<hr/>	
◆ Front Tyres residual:	80
<hr/>	

Functionality

Engine & electrical system functionality

◆ In quale stato è stata visionata la macchina:	Accesa e funzionante "al lavoro"
◆ Engine working conditions:	Very good
◆ Engine with oil leaks:	No
◆ Engine presents blowby:	No
◆ Oil-Water presence:	No
◆ Engine present smokiness:	No
◆ Radiator conditions:	Very good
◆ Starter motor conditions:	Very good
◆ Batteries/Cables conditions:	Very good
◆ Presence of electrical fault:	No

Functionality drive and rotation

◆ Hydraulic pump conditions:	Very good
◆ Engine travel conditions:	Very good
◆ Final drives conditions:	Very good
◆ Hydraulic joint conditions:	Very good
	Presence of leaks : No
◆ Gear switches go/back conditions:	Very Good

Engine & electrical system functionality

◆ Engine working conditions:	Very good
------------------------------	-----------

◆ Radiator conditions: Very good

◆ Starter motor conditions: Very good

Linkage Group

◆ Tenuta idraulica braccio (il braccio cala): No

◆ Boom structure: Very good

Presence of welding/cracks : No

◆ Flexible pipes conditions: Very good

◆ Lifting cylinders conditions: Very good

◆ Bucket cylinder conditions: Very good

◆ Pins & Bushings bucket conditions: Very good

◆ Bucket & Get conditions: Very good

◆ Quick Coupler conditions: Very good

◆ Funzionamento Impianto Ingrassaggio Automatico: Sì

Cabin and Tools

◆ Conditions internal cabin: Very good

◆ Lights & Windshield present issues: Presents and functioning

◆ Air conditioning & Filters conditions: Presents and functioning

◆ Back & side camera conditions: Present and functioning

Check 81/2008

- ◆ Condizioni freni: Molto Buono

- ◆ Condizioni freno di Stazionamento: Molto Buono

- ◆ Glass conditions: Excellent - no needs repair

- ◆ Lights conditions: Excellent - no needs repair

- ◆ Condizioni specchietti: Eccellente - non necessita riparazione

- ◆ Stepladders & handrails conditions: Very good

- ◆ Cameras conditions: Excellent - no needs repair

- ◆ Flashing conditions: Present and functioning

- ◆ Safety belt conditions: Present and valid

- ◆ Controls been modified: No

- ◆ Presence of Exclusion Control Lever: Yes

- If No, are control levers protected to accidental functionality? : Yes

- ◆ Are Tools Functional & Visible with tag: Yes

- ◆ Canopy completed and comes with keys and bolt: Yes

- ◆ All Pipes with no damage e/o scratches: Yes

- ◆ Batteries box shielded: Yes

- ◆ Acoustic alarm works properly: Yes

- ◆ Boardwalk presence: Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.