

## SALES REPORT: HAMM HD70#KHAMM - SN 47867 - Year 2001

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

### MACHINE DATA

---

**Model:** HD70#KHAMM

**Family:** ASPHALT COMPACTORS

**Serial Number:** 47867

**Order Number MU/MM:** MU00814837

**Construction year:** 2001

**Hour meter:** 1

**General residual conditions Truck/Tyres:** %

**Machine main application:**

**Location:** Conto deposito c/o Fornitore

**Rating:** ★☆☆☆☆

**Public price:** Ask

### MACHINE CONFIGURATION

---

● Machine type Standard - GP ● Quick Coupler System undefined ● Steering type 75 ● ● Tyres type undefined ● General Tyres Residual 1 ● 7500 Kg ● CE Mark ● CE Certificate ● Registration book & Licence plate Only Licence plate ADG656

**MACHINE PHOTOS**

---

◆ Il contaore e':

Rotto









## GENERAL APPEARANCE

◆ Painting Conditions:	Poor
◆ Counterweight conditions:	Poor
◆ Frame/Bumper conditions:	Not Working
◆ Condizioni Rullo anteriore (gomme se presenti):	Non Funzionante
◆ Door conditions:	NA - Not applicable
◆ Central joint:	Not working
◆ Fender/Mudguard conditions:	NA - Not applicable
◆ Other notes:	MACCHINA NON FUNZIONANTE -

## Functionality

---

### Engine & electrical system functionality

---

- ◆ In quale stato è stata visionata la macchina: Non funzionante

---

- ◆ Engine working conditions: Not working

---

- ◆ Engine with oil leaks: Yes

---

- ◆ Engine presents blowby: Yes

---

- ◆ Engine present smokiness: No

---

- ◆ Radiator conditions: Not working

---

- ◆ Condizioni Raschiarulli: NA - Non Applicabile

---

- ◆ Condizioni Supporti Antivibranti Tamburi: Non Funzionante

---

- ◆ Condizioni Impianto Irrorazione Acqua: Non Funzionante

---

- ◆ Batteries/Cables conditions: Very good

---

- ◆ Presence of electrical fault: Yes

---

### Functionality drive and rotation

---

- ◆ Hydraulic pump conditions: Not working

---

- ◆ Engine travel conditions: Not working

---

- ◆ Final drives conditions: Not working

---

- ◆ Gear switches go/back conditions: Not Working

---

- ◆ Funzionamento Impianto Vibrazione Tamburi: No

---

## Linkage Group

---

- ◆ Hydraulic conditions linkage group: Non Funzionante
  - ◆ Flexible pipes conditions: Not working
  - ◆ Funzionamento Impianto Ingrassaggio Automatico: No
- 

## Cabin and Tools

---

- ◆ Conditions internal cabin: Nt working
  - ◆ Lights & Windshield present issues: Not presents
  - ◆ Air contidioning & Filters conditions: Not functioning
  - ◆ Back & side camera conditions: Not functioning
- 

## Check 81/2008

---

- ◆ Condizioni freni: Non Funzionante
- ◆ Condizioni freno di Stazionamento: Non Funzionante
- ◆ Glass conditions: Excellent - no needs repair
- ◆ Lights conditions: Broken or Chipped - needs repair
- ◆ Condizioni specchietti: Mancanti
- ◆ Stepladders & handrails conditions: Not working
- ◆ Cameras conditions: Excellent - no needs repair
- ◆ Flashing conditions: Not functioning

---

◆ Safety belt conditions:	Not present/Broken
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	No
◆ Canopy completed and comes with keys and bolt:	No
◆ All Pipes with no damage e/o scratches:	No
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	No
◆ Boardwalk presence:	Not present

---

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.