

SALES REPORT: CATERPILLAR 432 - SN H7E01### - Year 2022

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: 432

Family: BACKHOE LOADER

Serial Number: H7E01###

Order Number MU/MM: MU00815183

Construction year: 2022

Hour meter: 4558

General residual conditions Truck/Tyres: %

Machine main application: Basic application

Machine availability date : 10/04/2026

Location: Coming in

Rating: ★★☆☆☆


Public price: Ask

MACHINE CONFIGURATION

• Steering type Command steering • Rops Close • Transmission type Hydrostatic • Tyres type • undefined • Ride Control • Quick coupler Hydraulic • Differential Type Self-Locking • Auxiliary Systems • Quick coupler Mechanic Cat • Bucket Standard 60 • Air Conditioning system • Product Link • Antitheft alarm • • CE Mark • CE Certificate • Use and maintenance manual • Registration book & Licence plate Registration book & Licence plate

MACHINE PHOTOS











GENERAL APPEARANCE

◆	Painting Conditions:	Good
---	----------------------	------

◆	Frame/Bumper conditions:	Good
---	--------------------------	------

◆	Door conditions:	Good
---	------------------	------

◆	Fender/Mudguard conditions:	Good
---	-----------------------------	------

Tyres

◆	N/D	50
---	-----	----

◆	N/D	50
---	-----	----

Functionality

Engine & electrical system functionality

◆	N/D	Accesa e funzionante "al lavoro"
---	-----	----------------------------------

◆	N/D	Good
---	-----	------

◆	N/D	No
---	-----	----

◆	N/D	No
---	-----	----

◆	N/D	No
---	-----	----

◆	N/D	No
---	-----	----

◆	N/D	Good
---	-----	------

◆	N/D	Good
---	-----	------

◆	N/D	Good
---	-----	------

◆ N/D	Non Presente
-------	--------------

Functionality drive and rotation

◆ N/D	Good
-------	------

◆ N/D	Good
-------	------

◆ N/D	Good
-------	------

Presence of leaks : No

◆ N/D	Good
-------	------

◆ N/D	Buono
-------	-------

Linkage Group

◆ N/D	No
-------	----

◆ N/D	Very good
-------	-----------

Presence of welding/cracks : No

◆ N/D	Good
-------	------

◆ N/D	Good
-------	------

Leaks : No

◆ N/D	Good
-------	------

Leaks : No

◆ N/D	Very good
-------	-----------

◆ N/D	Good
-------	------

◆ N/D	Good
-------	------

◆ N/D	Good
-------	------

◆ N/D		No
-------	--	----

Linkage Group

◆ N/D		No
-------	--	----

◆ N/D		Buono
-------	--	-------

◆ N/D		Good
-------	--	------

Presence of welding/cracks : No

◆ N/D		Good
-------	--	------

◆ N/D		Good
-------	--	------

Leaks : No

◆ N/D		Buono
-------	--	-------

◆ N/D		Good
-------	--	------

Leaks : No

◆ N/D		Good
-------	--	------

◆ N/D		Buono
-------	--	-------

◆ N/D		Good
-------	--	------

◆ N/D		Good
-------	--	------

◆ N/D		Poor
-------	--	------

◆ N/D		No
-------	--	----

Cabin and Tools

◆ Conditions internal cabin:		Good
------------------------------	--	------

◆ Lights & Windshield present issues:	Presents and functioning
---------------------------------------	--------------------------

◆ Air contidioning & Filters conditions:	Presents and functioning
--	--------------------------

Check 81/2008

◆ Condizioni freni:	Buono
---------------------	-------

◆ Condizioni freno di Stazionamento:	Buono
--------------------------------------	-------

◆ Glass conditions:	Excellent - no needs repair
---------------------	-----------------------------

◆ Lights conditions:	Excellent - no needs repair
----------------------	-----------------------------

◆ Condizioni specchietti:	Eccellente - non necessita riparazione
---------------------------	--

◆ Stepladders & handrails conditions:	Good
---------------------------------------	------

◆ Cameras conditions:	Excellent - no needs repair
-----------------------	-----------------------------

◆ Flashing conditions:	Present and functioning
------------------------	-------------------------

◆ Safety belt conditions:	Present and valid
---------------------------	-------------------

◆ Controls been modified:	No
---------------------------	----

◆ Presence of Exclusion Control Lever:	Yes
--	-----

If No, are control levers protected to accidental funcionality? : Yes

◆ Are Tools Functional & Visible with tag:	No
--	----

◆ Canopy completed and comes with keys and bolt:	Yes
--	-----

◆ All Pipes with no damage e/o scratches:	Yes
---	-----

◆ Batteries box shielded:	Yes
---------------------------	-----

◆ Acustic alarm works properly:	Yes
---------------------------------	-----

◆ Boardwalk presence:

Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.