

SALES REPORT: CATERPILLAR 924H - SN HXC02### - Year 2011

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: 924H

Family: SMALL WHEEL LOADER

Serial Number: HXC02###

Order Number MU/MM: MU00817963

Construction year: 2011

Hour meter: 6629

General residual conditions Truck/Tyres: 40 %

Machine main application: Heavy application

Machine availability date : 12/03/2026

Location: Coming in

Rating: ★★☆☆☆

Public price: Ask

MACHINE CONFIGURATION

● Machine type Standard - GP ● Steering type Command steering joystick Presence of Command Steering No ● Differential Type Self-Locking ● Transmission type Automatic ● Ride Control ● Auxiliary Systems ● Quick Coupler System ● Bucket Standard 2500 Get Cover Blade ● Tyres type Standard ● General Tyres Residual 40 20.5r25 Michelin e triangle ● Rops Close ● Air Conditioning system ● 11700 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual ● Registration book & Licence plate Registration book & Licence plate Ajc777 ● AVAILABLE FROM APRIL

MACHINE PHOTOS

◆ Il contaore e':

Funzionante









GENERAL APPEARANCE

- ◆ Painting Conditions: Good

- ◆ Counterweight conditions: Good

- Needs painting? : No

- ◆ Frame/Bumper conditions: Good

- ◆ Door conditions: Poor

- ◆ Central joint: Good

- ◆ Fender/Mudguard conditions: Good

- ◆ Other notes: Carrozzeria con punti di ruggine sulla cabina e alcuni danni sulle bandinelle

Tyres

◆ Front Tyres residual: 50

◆ Front Tyres residual: 40

Functionality

Engine & electrical system functionality

◆ In quale stato è stata visionata la macchina: Accesa e funzionante "al lavoro"

◆ Engine working conditions: Good

◆ Engine with oil leaks: No

◆ Engine presents blowby: No

◆ Oil-Water presence: No

◆ Engine present smokiness: No

◆ Radiator conditions: Good

◆ Starter motor conditions: Good

◆ Batteries/Cables conditions: Good

◆ Presence of electrical fault: No

◆ Annotazioni su: Benna standard ma non era in cantiere , condizioni buone

Functionality drive and rotation

◆ Hydraulic pump conditions: Good

◆ Engine travel conditions: Good

◆ Final drives conditions: Good

◆ Hydraulic joint conditions: Good

Presence of leaks : No

◆ Gear switches go/back conditions: Good

Engine & electrical system functionality

◆ Engine working conditions: Good

◆ Radiator conditions: Good

◆ Starter motor conditions: Good

Linkage Group

◆ Tenuta idraulica braccio (il braccio cala): No

◆ Boom structure: Good

Presence of welding/cracks : No

◆ Flexible pipes conditions: Good

◆ Lifting cylinders conditions: Good

◆ Bucket cylinder conditions: Good

◆ Pins & Bushings bucket conditions: Good

◆ Bucket & Get conditions: Good

◆ Quick Coupler conditions: NA - Not applicable

◆ Funzionamento Impianto Ingrassaggio Automatico: No

Cabin and Tools

◆ Conditions internal cabin:	Good
◆ Lights & Windshield present issues:	Presents and functioning
◆ Air conditioning & Filters conditions:	Presents and functioning
◆ Back & side camera conditions:	Not functioning

Check 81/2008

◆ Condizioni freni:	Buono
◆ Condizioni freno di Stazionamento:	Buono
◆ Glass conditions:	Broken or Chipped - needs repair
◆ Lights conditions:	Excellent - no needs repair
◆ Condizioni specchietti:	Rotto o Scheggiato - necessita riparazione
◆ Stepladders & handrails conditions:	Good
◆ Cameras conditions:	Broken or Chipped - needs repair
◆ Flashing conditions:	Not functioning
◆ Safety belt conditions:	Present and valid
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes

◆ All Pipes with no damage e/o scratches: Yes

◆ Batteries box shielded: Yes

◆ Acoustic alarm works properly: Yes

◆ Boardwalk presence: Present and functioning

◆ Annotazioni sul: Parafanghi smontati ma presenti

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.