

## SALES REPORT: CATERPILLAR 319C - SN KGL00### - Year 2007

This Report is a summary about observations came out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

#### MACHINE DATA

---

**Model:** 319C

**Family:** SMALL EXCAVATOR

**Serial Number:** KGL00###

**Order Number MU/MM:** MU00818100

**Construction year:** 2007

**Hour meter:** 7238

**General residual conditions Truck/Tyres:** 50 %

**Machine main application:** Basic application

**Machine availability date :** 27/03/2026

**Location:** Coming in

**Rating:** ★★☆☆☆

**Public price:** 52.000 €

#### MACHINE CONFIGURATION

---

• Machine type Standard • Boom type Triple boom • Boom check valves • Stick check valves • Plant features Versatility • Quick coupler Mechanic Cat cw 40 • Bucket Standard 1300mm Get Teeth • Truck type Fixed • General Truck Residual 50% • Cabin type Fixed standard • Air Conditioning system • Antitheft alarm • 21800 Kg • CE Mark • CE Certificate • Use and maintenance manual

**MACHINE PHOTOS**

---

◆ Il contaore è:

Funzionante





## GENERAL APPEARANCE

---

- ◆ Painting Conditions Good

---

- ◆ Counterweight conditions: Good

---

- ◆ Frame/Bumper conditions: Good

---

## TRUCK

---

◆ Sprockets residual:	50
◆ Front idler wheel residual:	45
◆ Rollers upper/bottom residual:	40
◆ Chains residual:	45

---

### Right side

---

◆ Door conditions (right):	Good
◆ Spar conditions:	Good

---

### Left side

---

◆ Door conditions (left):	Good
◆ Door conditions (left):	Good
◆ Spar conditions (left):	Good
◆ Hood/Armor bottom conditions:	Present and intact

---

## Functionality

---

### Engine & electrical system functionality

---

◆ In quale stato è stata visionata la macchina:	Accesa e provata per ispezione
◆ Engine working conditions:	Good
◆ Engine with oil leaks:	No

---

- ◆ Engine presents blowby: No  

---
- ◆ Oil-Water presence: No  

---
- ◆ Engine present smokiness: No  

---
- ◆ Radiator conditions: Good  

---
- ◆ Starter motor conditions: Good  

---
- ◆ Batteries/Cables conditions: Good  

---
- ◆ Presence of electrical fault: No  

---

**Functionality drive and rotation**

---

- ◆ Hydraulic pump conditions: Good  

---
- ◆ Engine rotation conditions: Good  

---
- ◆ Engine travel conditions: Good  

---
- ◆ Final drives conditions: Good  

---
- ◆ Hydraulic joint conditions: Good  
Presence of leaks : No  

---
- ◆ Hydraulic joint conditions: Good  
Presence of leaks : No  

---

**Linkage Group**

---

- ◆ Hydraulic conditions linkage group: No  

---
- ◆ Boom structure: Good  
Presence of welding/cracks : No  

---
- ◆ Stick structure: Good

Presence of welding/cracks : No

◆ Flexible pipes conditions:	Good
◆ Boom cylinders conditions:	Good Leaks : No
◆ Stick cylinder conditions:	Good Leaks : No
◆ Bucket cylinder conditions:	Good Leaks : No
◆ Pins & Bushings boom conditions:	Good
◆ Pins & Bushings stick conditions:	Good
◆ Pins & Bushings bucket conditions:	Good
◆ Bucket & Get conditions:	Good
◆ Quick Coupler conditions:	Good
◆ Auto Lube working conditions:	No

### Cabin and Tools

◆ Conditions internal cabin:	Good
◆ Flashing presents issues:	No
◆ Lights & Windshield present issues:	Presents and functioning
◆ Air conditioning is working:	Presente e funzionante
◆ Back & side camera conditions:	Not functioning

◆ Glass conditions:	Excellent - no needs repair
◆ Lights conditions:	Excellent - no needs repair
◆ Rear view mirrors conditions:	Excellent - no needs repair
◆ Stepladders & handrails conditions:	Good
◆ Cameras conditions:	Broken or Chipped - needs repair
◆ Flashing conditions:	Not functioning
◆ Safety belt conditions:	Present and expired
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	Yes
◆ Boardwalk presence:	Present and functioning

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.