

## SALES REPORT: CATERPILLAR 966M XE - SN DZL00580 - Year 2019

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

#### MACHINE DATA

---

**Model:** 966M XE

**Family:** MEDIUM WHEEL LOADER

**Serial Number:** DZL00580

**Order Number MU/MM:** MU00819204

**Construction year:** 2019

**Hour meter:** 18540

**General residual conditions Truck/Tyres:** 10 %

**Machine main application:** Basic application

**Location:** Stock Brescia

**Rating:** ★☆☆☆☆

**Public price:** Ask

#### MACHINE CONFIGURATION

---

● Machine type Standard - GP ● Steering type Joystick Presence of Command Steering Yes ● Differential Type Self-Locking ● Transmission type Automatic ● Ride Control ● Bucket Standard 3 MT 4,2 MC Get Cover Blade ● Tyres type Standard ● General Tyres Residual 10 26.5 r25 ● Rops Close ● Air Conditioning system ● Auto Lube system ● Weight Scale ● Product Link ● 23200 Kg ● CE Mark ● CE Certificate ● EPA Tag ● Use and maintenance manual ● Registration book & Licence plate undefined

**MACHINE PHOTOS**

---

◆ Il contaore e':

Funzionante







- ◆ Painting Conditions: Good

---

- ◆ Counterweight conditions: Good

---

- Needs painting? : No

---

- ◆ Frame/Bumper conditions: Good

---

- ◆ Door conditions: Poor

---

- ◆ Central joint: Good

---

- ◆ Fender/Mudguard conditions: Good

---

- ◆ Other notes: Vetro anteriore dx,centrale ,sx da cambiare

---

### Tyres

---

- ◆ Front Tyres residual: 10

---

- ◆ Front Tyres residual: 1

---

### Functionality

---

#### Engine & electrical system functionality

---

- ◆ In quale stato è stata visionata la macchina: Accesa e provata per ispezione

---

- ◆ Engine working conditions: Poor

---

- ◆ Engine with oil leaks: No

---

- ◆ Engine presents blowby: No

---

- ◆ Oil-Water presence: No

---

- ◆ Engine present smokiness: No

---

- ◆ Radiator conditions: Good

---

- ◆ Starter motor conditions: Good

---

- ◆ Batteries/Cables conditions: Good

---

- ◆ Presence of electrical fault: No

---

**Functionality drive and rotation**

---

- ◆ Hydraulic pump conditions: Good

---

- ◆ Engine travel conditions: Poor

---

- ◆ Final drives conditions: Good

---

- ◆ Hydraulic joint conditions: Poor

Presence of leaks : No

---

- ◆ Gear switches go/back conditions: Poor

---

**Engine & electrical system functionality**

---

- ◆ Engine working conditions: Good

---

- ◆ Radiator conditions: Good

---

- ◆ Starter motor conditions: Good

---

**Linkage Group**

---

- ◆ Tenuta idraulica braccio (il braccio cala): No

---

- ◆ Boom structure: Good

Presence of welding/cracks : No

---

- ◆ Flexible pipes conditions: Good

---

- ◆ Lifting cylinders conditions: Good

---

- ◆ Bucket cylinder conditions: Good

---

- ◆ Pins & Bushings bucket conditions: Good

---

- ◆ Bucket & Get conditions: Good

---

- ◆ Quick Coupler conditions: Good

---

- ◆ Funzionamento Impianto Ingrassaggio Automatico: Sì

---

- ◆ Annotazioni su: Trasmissione da revisionare

---

## Cabin and Tools

---

- ◆ Conditions internal cabin: Good

---

- ◆ Lights & Windshield present issues: Presents and functioning

---

- ◆ Air conditioning & Filters conditions: Presents and functioning

---

- ◆ Back & side camera conditions: Present and functioning

---

## Check 81/2008

---

- ◆ Condizioni freni: Buono

---

- ◆ Condizioni freno di Stazionamento: Buono

---

- ◆ Glass conditions: Excellent - no needs repair

---

- ◆ Lights conditions: Excellent - no needs repair

---

◆ Condizioni specchietti:	Eccellente - non necessita riparazione
◆ Stepladders & handrails conditions:	Good
◆ Cameras conditions:	Excellent - no needs repair
◆ Flashing conditions:	Present and functioning
◆ Safety belt conditions:	Present and expired
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	Yes
◆ Boardwalk presence:	Present and functioning

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.