

SALES REPORT: CATERPILLAR 340 DEM - SN WLE10### - Year 2022

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: 340 DEM

Family: MEDIUM EXCAVATOR

Serial Number: WLE10###

Order Number MU/MM: MU00820365

Construction year: 2022

Hour meter: 3069

General residual conditions Truck/Tyres: 70 %

Machine main application: Heavy application

Machine availability date : 27/04/2026

Location: Coming in

Rating: ★★☆☆☆

Public price: 650.000 €

MACHINE CONFIGURATION

● Machine type Demolition ● Boom type Demolition retrofit ● Boom check valves ● Stick check valves ● Plant features Versatility linea drenaggio ● Quick coupler Hydraulic ● Bucket Standard Get Teeth ● Truck type Hydraulic extendible ● General Truck Residual 70% ● Cabin type Hydraulic lift ● Cabin fog Front superiore ● Air Conditioning system ● Auto Lube system ● Product Link ● Antitheft alarm ● 58400 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual Presenti entrambi i bracci, sia monoblocco da scavo che lungo da demolizione.

MACHINE PHOTOS

◆ Il contaore è:

Funzionante











GENERAL APPEARANCE

◆ Painting Conditions Good

◆ Counterweight conditions: Good

◆ Frame/Bumper conditions: Good

TRUCK

◆ Sprockets residual: 70

◆ Front idler wheel residual: 70

◆ Rollers upper/bottom residual: 70

◆ Chains residual: 70

Right side

◆ Door conditions (right): Good

◆ Spar conditions: Good

Left side

◆ Door conditions (left): Good

◆ Door conditions (left): Good

◆ Spar conditions (left): Good

◆ Hood/Armor bottom conditions: Present and intact

Functionality

Engine & electrical system functionality

◆ In quale stato è stata visionata la macchina:	Accesa e provata per ispezione
<hr/>	
◆ Engine working conditions:	Good
<hr/>	
◆ Engine with oil leaks:	No
<hr/>	
◆ Engine presents blowby:	No
<hr/>	
◆ Oil-Water presence:	No
<hr/>	
◆ Engine present smokiness:	No
<hr/>	
◆ Radiator conditions:	Good
<hr/>	
◆ Starter motor conditions:	Good
<hr/>	
◆ Batteries/Cables conditions:	Good
<hr/>	
◆ Presence of electrical fault:	No
<hr/>	

Functionality drive and rotation

◆ Hydraulic pump conditions:	Good
<hr/>	
◆ Engine rotation conditions:	Good
<hr/>	
◆ Engine travel conditions:	Good
<hr/>	
◆ Final drives conditions:	Good
<hr/>	
◆ Hydraulic joint conditions:	Good
	Presence of leaks : No
<hr/>	
◆ Hydraulic joint conditions:	Good
	Presence of leaks : No
<hr/>	

Linkage Group

- ◆ Hydraulic conditions linkage group: No

- ◆ Boom structure: Good
Presence of welding/cracks : No

- ◆ Stick structure: Good
Presence of welding/cracks : No

- ◆ Flexible pipes conditions: Good

- ◆ Boom cylinders conditions: Good
Leaks : No

- ◆ Stick cylinder conditions: Good
Leaks : No

- ◆ Bucket cylinder conditions: Good
Leaks : No

- ◆ Pins & Bushings boom conditions: Good

- ◆ Pins & Bushings stick conditions: Good

- ◆ Pins & Bushings bucket conditions: Good

- ◆ Bucket & Get conditions: Good

- ◆ Quick Coupler conditions: Good

- ◆ Auto Lube working conditions: SI

Cabin and Tools

- ◆ Conditions internal cabin: Very good

◆ Flashing presents issues:	No
◆ Lights & Windshield present issues:	Presents and functioning
◆ Air conditioning is working:	Presente e funzionante
◆ Back & side camera conditions:	Present and functioning

Check 81/2008

◆ Glass conditions:	Excellent - no needs repair
◆ Lights conditions:	Excellent - no needs repair
◆ Rear view mirrors conditions:	Excellent - no needs repair
◆ Stepladders & handrails conditions:	Very good
◆ Cameras conditions:	Excellent - no needs repair
◆ Flashing conditions:	Not functioning
◆ Safety belt conditions:	Present and expired
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	Yes
◆ Boardwalk presence:	Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.