

SALES REPORT: VOLVO L120H - SN 120HJ00017### - Year 2019

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: L120H

Family: MEDIUM WHEEL LOADER

Serial Number: 120HJ00017###

Order Number MU/MM: MU00823108

Construction year: 2019

Hour meter: 1442

General residual conditions Truck/Tyres: 80 %

Machine main application: Basic application

Machine availability date : 31/03/2026

Location: Coming in

Rating: ★★☆☆☆

Public price: Ask

MACHINE CONFIGURATION

• Machine type Standard - GP • Steering type Command steering • Differential Type Self-Locking • Transmission type Automatic • Ride Control • Bucket Standard Get undefined • Tyres type Standard • General Tyres Residual 80 25.5 R 25 Michelin • Rops Close • Air Conditioning system • Auto Lube system • Weight Scale • Product Link • 21600 Kg • CE Mark • CE Certificate • Use and maintenance manual • Registration book & Licence plate Registration book & Licence plate AL652H • AVAILABLE FROM JUNE

MACHINE PHOTOS

◆ Il contaore e':

Funzionante



GENERAL APPEARANCE

◆ Painting Conditions:

Good

◆ Counterweight conditions: Good
Needs painting? : No

◆ Frame/Bumper conditions: Good

◆ Door conditions: Good

◆ Central joint: Very good

◆ Fender/Mudguard conditions: Good

Tyres

◆ Front Tyres residual: 80

◆ Front Tyres residual: 80

Functionality

Engine & electrical system functionality

◆ In quale stato è stata visionata la macchina: Accesa e funzionante "al lavoro"

◆ Engine working conditions: Good

◆ Engine with oil leaks: No

◆ Engine presents blowby: No

◆ Oil-Water presence: No

◆ Engine present smokiness: No

◆ Radiator conditions: Good

◆ Starter motor conditions: Good

◆ Batteries/Cables conditions: Good

◆ Presence of electrical fault: No

Functionality drive and rotation

◆ Hydraulic pump conditions: Good

◆ Engine travel conditions: Good

◆ Final drives conditions: Good

◆ Hydraulic joint conditions: Good

Presence of leaks : No

◆ Gear switches go/back conditions: Good

Engine & electrical system functionality

◆ Engine working conditions: Good

◆ Radiator conditions: Good

◆ Starter motor conditions: Good

Linkage Group

◆ Tenuta idraulica braccio (il braccio cala): No

◆ Boom structure: Good

Presence of welding/cracks : No

◆ Flexible pipes conditions: Good

◆ Lifting cylinders conditions: Good

| | |
|---|---------------------|
| ◆ Bucket cylinder conditions: | Good |
| ◆ Pins & Bushings bucket conditions: | Good |
| ◆ Bucket & Get conditions: | Good |
| ◆ Quick Coupler conditions: | NA - Not applicable |
| ◆ Funzionamento Impianto Ingrassaggio Automatico: | Sì |

Cabin and Tools

| | |
|--|--------------------------|
| ◆ Conditions internal cabin: | Good |
| ◆ Lights & Windshield present issues: | Presents and functioning |
| ◆ Air conditioning & Filters conditions: | Presents and functioning |
| ◆ Back & side camera conditions: | Present and functioning |

Check 81/2008

| | |
|---------------------------------------|--|
| ◆ Condizioni freni: | Buono |
| ◆ Condizioni freno di Stazionamento: | Buono |
| ◆ Glass conditions: | Excellent - no needs repair |
| ◆ Lights conditions: | Excellent - no needs repair |
| ◆ Condizioni specchietti: | Eccellente - non necessita riparazione |
| ◆ Stepladders & handrails conditions: | Good |
| ◆ Cameras conditions: | Excellent - no needs repair |

| | |
|--|-------------------------|
| ◆ Flashing conditions: | Present and functioning |
| ◆ Safety belt conditions: | Present and valid |
| ◆ Controls been modified: | No |
| ◆ Presence of Exclusion Control Lever: | Yes |
| ◆ Are Tools Functional & Visible with tag: | Yes |
| ◆ Canopy completed and comes with keys and bolt: | Yes |
| ◆ All Pipes with no damage e/o scratches: | Yes |
| ◆ Batteries box shielded: | Yes |
| ◆ Acoustic alarm works properly: | Yes |
| ◆ Boardwalk presence: | Present and functioning |

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.