

## SALES REPORT: CATERPILLAR 924G - SN 3PZ01### - Year 2003

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

### MACHINE DATA

---

**Model:** 924G

**Family:** SMALL WHEEL LOADER

**Serial Number:** 3PZ01###

**Order Number MU/MM:** MU00823499

**Construction year:** 2003

**Hour meter:** 13185

**General residual conditions Truck/Tyres:** 40 %

**Machine main application:** Basic application

**Machine availability date :** 29/04/2026

**Location:** Coming in

**Rating:** ★★☆☆☆

**Public price:** Ask

### MACHINE CONFIGURATION

---

● Machine type Standard - GP ● Steering type Command steering Presence of Command Steering No ● Differential Type Controlled Slippage ● Transmission type Automatic ● Quick Coupler System ● Quick coupler Hydraulic CAT IT ● Bucket Standard MC2,1 Get Cover Blade ● Tyres type Standard ● General Tyres Residual 40 20,5R25 DYNAMAX ● Rops Close ● Air Conditioning system ● Weight Scale ● 13000 Kg ● CE Mark ● CE Certificate ● Registration book & Licence plate Registration book & Licence plate ACT518 ● AVAILABLE FROM MAY

**MACHINE PHOTOS**

---

◆ Il contaore e':

Funzionante







## GENERAL APPEARANCE

---

◆ Painting Conditions:	Poor
<hr/>	
◆ Counterweight conditions:	Good
	Needs painting? : Yes
<hr/>	
◆ Frame/Bumper conditions:	Good
<hr/>	
◆ Door conditions:	Poor
<hr/>	
◆ Central joint:	Poor
<hr/>	
◆ Fender/Mudguard conditions:	Good
<hr/>	
◆ Other notes:	GIOCO NELLA NORMA SULLO SNODO CENTRALE
<hr/>	

## Tyres

---

◆ Front Tyres residual:	40
<hr/>	
◆ Front Tyres residual:	40
<hr/>	

## Functionality

---

### Engine & electrical system functionality

---

- ◆ In quale stato è stata visionata la macchina: Accesa e funzionante "al lavoro"

---
- ◆ Engine working conditions: Good

---
- ◆ Engine with oil leaks: Yes  
If Yes, where : PARTE ALTA DEL MOTORE

---
- ◆ Engine presents blowby: Yes

---
- ◆ Oil-Water presence: No

---
- ◆ Engine present smokiness: No

---
- ◆ Radiator conditions: Good

---
- ◆ Starter motor conditions: Good

---
- ◆ Batteries/Cables conditions: Good

---
- ◆ Presence of electrical fault: No

---
- ◆ Annotazioni su: DA RIVEDERE ALCUNI INTERRUTTORI COMANDI TERGICRISTALLI E FARI

---

### Functionality drive and rotation

---

- ◆ Hydraulic pump conditions: Good

---
- ◆ Engine travel conditions: Good

---
- ◆ Final drives conditions: Good

---
- ◆ Hydraulic joint conditions: Good  
Presence of leaks : No

---
- ◆ Gear switches go/back conditions: Good

---

### Engine & electrical system functionality

---

- ◆ Engine working conditions: Good

---

- ◆ Radiator conditions: Poor

---

- ◆ Starter motor conditions: Poor

---

### Linkage Group

---

- ◆ Tenuta idraulica braccio (il braccio cala): No

---

- ◆ Boom structure: Good  
Presence of welding/cracks : No

---

- ◆ Flexible pipes conditions: Good

---

- ◆ Lifting cylinders conditions: Good

---

- ◆ Bucket cylinder conditions: Good

---

- ◆ Pins & Bushings bucket conditions: Poor

---

- ◆ Bucket & Get conditions: Poor

---

- ◆ Quick Coupler conditions: Good

---

- ◆ Funzionamento Impianto Ingrassaggio Automatico: No

---

### Cabin and Tools

---

- ◆ Conditions internal cabin: Poor

---

- Other notes : BLOCCO STERZO ROTTO ...SEDILE DA RIVESTIRE ...

---

- ◆ Lights & Windshield present issues: Present and not functioning

◆ Air conditioning & Filters conditions: Present and not functioning

◆ Back & side camera conditions: Not functioning

**Check 81/2008**

---

◆ Condizioni freni: Buono

◆ Condizioni freno di Stazionamento: Scarso

◆ Glass conditions: Broken or Chipped - needs repair

◆ Lights conditions: Broken or Chipped - needs repair

◆ Condizioni specchietti: Rotto o Scheggiato - necessita riparazione

◆ Stepladders & handrails conditions: Good

◆ Cameras conditions: Broken or Chipped - needs repair

◆ Flashing conditions: Not functioning

◆ Safety belt conditions: Present and expired

◆ Controls been modified: No

◆ Presence of Exclusion Control Lever: Yes

If No, are control levers protected to accidental functionality? : Yes

◆ Are Tools Functional & Visible with tag: Yes

◆ Canopy completed and comes with keys and bolt: Yes

◆ All Pipes with no damage e/o scratches: Yes

◆ Batteries box shielded: Yes

◆ Acoustic alarm works properly: Yes

---

◆ Boardwalk presence:

Present and bashee

---

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.