

SALES REPORT: CATERPILLAR 962G - SN 3BS00302 - Year 1998

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: 962G

Family: MEDIUM WHEEL LOADER

Serial Number: 3BS00302

Order Number MU/MM: MU00823768

Construction year: 1998

Hour meter: 25000

General residual conditions Truck/Tyres: 70 %

Machine main application: Basic application

Location: Stock CATANIA

Rating: ★★☆☆☆

Public price: 41.000 €

MACHINE CONFIGURATION

● Machine type Standard - GP ● Steering type Command steering ● Differential Type Standard ● Transmission type Manual ● Bucket Standard 3000 mm Get Cover Blade ● Tyres type Standard ● General Tyres Residual 70 23.5 Triangle ● Rops Close ● 20000 Kg ● CE Mark ● CE Certificate ● Registration book & Licence plate
Registration book & Licence plate

MACHINE PHOTOS

◆ Il contaore e':

Funzionante











◆ Central joint: Good

◆ Fender/Mudguard conditions: Good

Tyres

◆ Front Tyres residual: 60

◆ Front Tyres residual: 80

Functionality

Engine & electrical system functionality

◆ In quale stato è stata visionata la macchina: Accesa e funzionante "al lavoro"

◆ Engine working conditions: Good

◆ Engine with oil leaks: No

◆ Engine presents blowby: No

◆ Oil-Water presence: No

◆ Engine present smokiness: No

◆ Radiator conditions: Poor

◆ Starter motor conditions: Good

◆ Batteries/Cables conditions: Good

◆ Presence of electrical fault: No

Functionality drive and rotation

- ◆ Hydraulic pump conditions: Good

- ◆ Engine travel conditions: Good

- ◆ Final drives conditions: Good

- ◆ Hydraulic joint conditions: Good
Presence of leaks : No

- ◆ Gear switches go/back conditions: Good

Engine & electrical system functionality

- ◆ Engine working conditions: Good

- ◆ Radiator conditions: Good

- ◆ Starter motor conditions: Good

Linkage Group

- ◆ Tenuta idraulica braccio (il braccio cala): No

- ◆ Boom structure: Good
Presence of welding/cracks : No

- ◆ Flexible pipes conditions: Good

- ◆ Lifting cylinders conditions: Good

- ◆ Bucket cylinder conditions: Good

- ◆ Pins & Bushings bucket conditions: Good

- ◆ Bucket & Get conditions: Good

- ◆ Quick Coupler conditions: NA - Not applicable

- ◆ Funzionamento Impianto Ingrassaggio Automatico: No

- ◆ Annotazioni su:
Revisione certificata motore 2 anni fa. Macchina da poco uscita da nostra officina per lavorazioni varie (€ 17.000,00)

Cabin and Tools

- ◆ Conditions internal cabin: Good

- ◆ Lights & Windshield present issues: Presents and functioning

- ◆ Air conditioning & Filters conditions: Present and not functioning

- ◆ Back & side camera conditions: Not functioning

Check 81/2008

- ◆ Condizioni freni: Buono

- ◆ Condizioni freno di Stazionamento: Buono

- ◆ Glass conditions: Excellent - no needs repair

- ◆ Lights conditions: Excellent - no needs repair

- ◆ Condizioni specchietti: Eccellente - non necessita riparazione

- ◆ Stepladders & handrails conditions: Good

- ◆ Cameras conditions: Broken or Chipped - needs repair

- ◆ Flashing conditions: Not functioning

◆ Safety belt conditions:	Present and expired
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	Yes
◆ Boardwalk presence:	Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.