

SALES REPORT: CATERPILLAR CB7 - SN NLJ00101 - Year 2017

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: CB7

Family: ASPHALT COMPACTORS

Serial Number: NLJ00101

Order Number MU/MM: MU00823837

Construction year: 2017

Hour meter: 600

General residual conditions Truck/Tyres: %

Machine main application:

Location: Stock Padova

Rating: ★★☆☆☆

Public price: 65.000 €

MACHINE CONFIGURATION

● Machine type Standard - GP ● Quick Coupler System undefined ● Steering type 7990 ● ● ● Tyres type undefined ● General Tyres Residual 1 ● 7990 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual ● Registration book & Licence plate Registration book & Licence plate AKM978 Monitor rotto , sedile da sistemare

MACHINE PHOTOS

◆ Il contaore e':

Rotto









GENERAL APPEARANCE

- ◆ Painting Conditions: Very Good

- ◆ Counterweight conditions: Very good

- ◆ Frame/Bumper conditions: Very Good

- ◆ Condizioni Rullo anteriore (gomme se presenti): Molto Buono

◆ Door conditions: Very good

◆ Central joint: Very good

◆ Fender/Mudguard conditions: NA - Non Applicabile

Functionality

Engine & electrical system functionality

◆ In quale stato è stata visionata la macchina: Accesa e provata per ispezione

◆ Engine working conditions: Good

◆ Engine with oil leaks: No

◆ Engine presents blowby: No

◆ Engine present smokiness: No

◆ Radiator conditions: Good

◆ Condizioni Raschiarulli: Buono

◆ Condizioni Supporti Antivibranti Tamburi: Buono

◆ Condizioni Impianto Irrorazione Acqua: Buono

◆ Batteries/Cables conditions: Excellent

◆ Presence of electrical fault: No

Functionality drive and rotation

◆ Hydraulic pump conditions: Good

- ◆ Engine travel conditions: Good

- ◆ Final drives conditions: Good

- ◆ Gear switches go/back conditions: Good

- ◆ Funzionamento Impianto Vibrazione Tamburi: Si

Linkage Group

- ◆ Hydraulic conditions linkage group: Buono

- ◆ Flexible pipes conditions: Good

- ◆ Funzionamento Impianto Ingrassaggio Automatico: No

Cabin and Tools

- ◆ Conditions internal cabin: Good
Other notes : Sedile da sistemare, c'è una modifica da applicare .

- ◆ Lights & Windshield present issues: Presents and functioning

- ◆ Air conditioning & Filters conditions: Not functioning

- ◆ Back & side camera conditions: Not functioning

Check 81/2008

- ◆ Condizioni freni: Buono

- ◆ Condizioni freno di Stazionamento: Buono

- ◆ Glass conditions: Broken or Chipped - needs repair

◆ Lights conditions:	Excellent - no needs repair
◆ Condizioni specchietti:	Eccellente - non necessita riparazione
◆ Stepladders & handrails conditions:	Good
◆ Cameras conditions:	Broken or Chipped - needs repair
◆ Flashing conditions:	Not functioning
◆ Safety belt conditions:	Present and valid
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	No
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	Yes
◆ Boardwalk presence:	Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.