

SALES REPORT: CATERPILLAR AP300F - SN FRA00103 - Year 2019

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: AP300F

Family: ASPHALT PAVERS

Serial Number: FRA00103

Order Number MU/MM: MU00825829

Construction year: 2019

Hour meter: 4824

General residual conditions Truck/Tyres: %

Machine main application:

Location: Stock Brescia

Rating: ★★☆☆☆

Public price: 97.000 €

MACHINE CONFIGURATION

- Machine type Mass Excavator ● Boom type undefined ● Plant features ● Quick coupler ● Truck type undefined
- Product Link undefined non riscaldate ● EPA Tag ● 8500 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual

MACHINE PHOTOS







◆ Painting Conditions	Good
◆ Spar conditions:	Good
◆ Residual % - Tyres/Track:	50
◆ Residual % - Cushion:	50
◆ Seat condition:	Good
◆ Engine working conditions:	Good
◆ Radiator conditions:	Good
◆ Batteries/Cables conditions:	Good

Functionality

SCREED

◆ Hydraulic pump conditions:	1,75 3,42
◆ Brakes and steering clutch conditions:	20
◆ Engine travel conditions:	20
◆ Final drives conditions:	20
◆ Residuo % Nastri:	20
◆ Residuo % Fondi	20
◆ Apertura massima Allargamenti (se presenti):	No

Engine & electrical system functionality

◆ In quale stato è stata visionata la macchina: Accesa e provata per ispezione

◆ Engine working conditions: Good

◆ Engine with oil leaks: No

◆ Engine presents blowby: No

◆ Engine present smokiness: No

◆ Radiator conditions: Good

◆ Starter motor conditions: Good

◆ Batteries/Cables conditions: Good

◆ Presence of electrical fault: No

Functionality drive and rotation

◆ Hydraulic pump conditions: Good

◆ Engine travel conditions: Good

◆ Final drives conditions: Good

Linkage Group

◆ Boom structure: Good

Presenza di perdite? Se si, specificare da dove: : No

◆ Stick structure: Good

Presenza di perdite? Se si, specificare da dove: : No

◆ Flexible pipes conditions: Good

Presenza di perdite? Se si, specificare da dove: : No

◆ Boom cylinders conditions: Good

Check 81/2008

◆ Condizioni freni:	Buono
◆ Condizioni freno di Stazionamento:	Buono
◆ Lights conditions:	Excellent - no needs repair
◆ Condizioni specchietti:	Eccellente - non necessita riparazione
◆ Stepladders & handrails conditions:	Good
◆ Cameras conditions:	Excellent - no needs repair
◆ Flashing conditions:	Present and functioning
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	Yes
◆ Boardwalk presence:	Present and functioning
◆ Annotazioni su:	Catena dx da sostituire perché rotta

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.