

## SALES REPORT: CATERPILLAR 966M XE - SN FL200### - Year 2018

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

### MACHINE DATA

---

**Model:** 966M XE

**Family:** MEDIUM WHEEL LOADER

**Serial Number:** FL200###

**Order Number MU/MM:** MU00826937

**Construction year:** 2018

**Hour meter:** 15401

**General residual conditions Truck/Tyres:** 80 %

**Machine main application:** Basic application

**Machine availability date :** 14/08/2026

**Location:** Coming in

**Rating:** ★★☆☆☆

**Public price:** Ask

### MACHINE CONFIGURATION

---

● Machine type Standard - GP ● Steering type Joystick Presence of Command Steering No ● Differential Type Self-Locking ● Transmission type Automatic ● Ride Control ● Bucket Standard 4,8 MC Get Cover Blade ● Tyres type Rock ● General Tyres Residual 80 26.5 R 25 ● Rops Close ● Air Conditioning system ● Auto Lube system ● Weight Scale ● Product Link ● 23000 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual ● Registration book & Licence plate undefined ● AVAILABLE FROM JULY

## MACHINE PHOTOS

---

◆ Il contaore e':

Funzionante





**GENERAL APPEARANCE**

---

◆ Painting Conditions:	Good
<hr/>	
◆ Counterweight conditions:	Good
	Needs painting? : No
<hr/>	
◆ Frame/Bumper conditions:	Good
<hr/>	
◆ Door conditions:	Good
<hr/>	
◆ Central joint:	Good
<hr/>	
◆ Fender/Mudguard conditions:	Poor
<hr/>	
◆ Other notes:	PARAFANGO POST SX AMMACCATO
<hr/>	

**Tyres**

---

◆	N/D	80
---	-----	----

---

◆	N/D	80
---	-----	----

---

## Functionality

---

### Engine & electrical system functionality

---

◆	N/D	Accesa e funzionante "al lavoro"
---	-----	----------------------------------

---

◆	N/D	Good
---	-----	------

---

◆	N/D	No
---	-----	----

---

◆	N/D	No
---	-----	----

---

◆	N/D	No
---	-----	----

---

◆	N/D	No
---	-----	----

---

◆	N/D	Good
---	-----	------

---

◆	N/D	Good
---	-----	------

---

◆	N/D	Good
---	-----	------

---

◆	N/D	No
---	-----	----

---

### Functionality drive and rotation

---

◆	N/D	Good
---	-----	------

---

◆	N/D	NA - Not applicable
---	-----	---------------------

---

◆	N/D	Good
---	-----	------

---

◆ N/D Good

Presence of leaks : No

◆ N/D NA - Not Applicable

**Engine & electrical system functionality**

---

◆ N/D Good

◆ N/D Good

◆ N/D Poor

**Linkage Group**

---

◆ N/D No

◆ N/D Good

Presence of welding/cracks : No

◆ N/D Good

◆ N/D Good

◆ N/D Good

◆ N/D Good

◆ N/D Poor

◆ N/D NA - Not applicable

◆ N/D Si

**Cabin and Tools**

---

◆ Conditions internal cabin:	Good
◆ Lights & Windshield present issues:	Presents and functioning
◆ Air contidioning & Filters conditions:	Presents and functioning
◆ Back & side camera conditions:	Present and functioning

### Check 81/2008

◆ Condizioni freni:	Buono
◆ Condizioni freno di Stazionamento:	Buono
◆ Glass conditions:	Excellent - no needs repair
◆ Lights conditions:	Excellent - no needs repair
◆ Condizioni specchietti:	Eccellente - non necessita riparazione
◆ Stepladders & handrails conditions:	Good
◆ Cameras conditions:	Excellent - no needs repair
◆ Flashing conditions:	Present and functioning
◆ Safety belt conditions:	Present and valid
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes

---

◆ Acoustic alarm works properly: Yes

---

◆ Boardwalk presence: Present and functioning

---

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.