

## SALES REPORT: MANITOU MRT2145#KMANI - SN 1074### - Year 2022

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

### MACHINE DATA

---

**Model:** MRT2145#KMANI

**Family:** FIXED TELESCOPIC HANDLER

**Serial Number:** 1074###

**Order Number MU/MM:** MU00828070

**Construction year:** 2022

**Hour meter:** 679

**General residual conditions Truck/Tyres:** 85 %

**Machine main application:** Basic application

**Machine availability date :** 27/05/2026

**Location:** Coming in

**Rating:** ★★☆☆☆

**Public price:** 190.000 €

### MACHINE CONFIGURATION

---

● Machine type HLA ● Boom type Mono boom ● Boom check valves ● undefined ● Tyres type undefined ● Stabilizers 4 Stabilizers ● Auxiliary Systems ● Quick Coupler System ● Quick coupler Mechanic ● Bucket Standard 1000 litri 2,40m Get Cover Blade ● Forks ● Saddle attachment ● CE Certificate ● Tyres type Standard ● General Tyres Residual 85 vgt vft telescopico rotativo con portata massima 45 quintali e braccio da 21 metri completo di forche , piattaforma porta persone inclinabile con radiocomando e doppia batteria di alimentazione del radiocomando , organo idraulico con portata massima di 5 ton , benna a richiesta , documenti ispesl di messa in servizio , certificati ce di tutte le attrezzature ● Rops Close ● Air Conditioning system ● Product Link ● 14900 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual ● Registration book & Licence plate Registration book & Licence plate amh603

## MACHINE PHOTOS

◆ Il contaore e':

Funzionante







## GENERAL APPEARANCE

|                               |                      |
|-------------------------------|----------------------|
| ◆ Painting Conditions:        | Very Good            |
| ◆ Counterweight conditions:   | Very good            |
|                               | Needs painting? : No |
| ◆ Frame/Bumper conditions:    | Very Good            |
| ◆ Door conditions:            | Very good            |
| ◆ Fender/Mudguard conditions: | Very good            |

## Tyres

---

◆ Front Tyres residual: 85

---

◆ Front Tyres residual: 85

---

## Functionality

---

### Engine & electrical system functionality

---

◆ In quale stato è stata visionata la macchina: Accesa e provata per ispezione

---

◆ Engine working conditions: Very good

---

◆ Engine with oil leaks: No

---

◆ Engine presents blowby: No

---

◆ Oil-Water presence: No

---

◆ Engine present smokiness: No

---

◆ Radiator conditions: Very good

---

◆ Starter motor conditions: Very good

---

◆ Batteries/Cables conditions: Very good

---

◆ Presence of electrical fault: No

---

### Functionality drive and rotation

---

◆ Hydraulic pump conditions: Very good

---

◆ Engine travel conditions: Very good

---

◆ Final drives conditions: Very good

---

◆ Hydraulic joint conditions: NA - Not applicable

Presence of leaks : No

---

◆ Gear switches go/back conditions: Very Good

---

### Engine & electrical system functionality

---

◆ Engine working conditions: Very good

---

◆ Radiator conditions: Very good

---

### Linkage Group

---

◆ Tenuta idraulica braccio (il braccio cala): No

---

◆ Boom structure: Very good

Photos

Presence of welding/cracks : No

FOTO IN AGGIORNAMENTO



FOTO IN AGGIORNAMENTO



---

◆ Flexible pipes conditions: Very good

---

◆ Lifting cylinders conditions: Very good

---

◆ Bucket cylinder conditions: Very good

---

◆ Pins & Bushings bucket conditions: Very good

---

|   |      |
|---|------|
| ◆ Bucket & Get conditions:                        | Good |
| ◆ Quick Coupler conditions:                       | Good |
| ◆ Funzionamento Impianto Ingrassaggio Automatico: | No   |

---

### Cabin and Tools

---

|  |                          |
|--|--------------------------|
| ◆ Conditions internal cabin:             | Very good                |
| ◆ Lights & Windshield present issues:    | Presents and functioning |
| ◆ Air contidioning & Filters conditions: | Presents and functioning |
| ◆ Back & side camera conditions:         | Present and functioning  |

---

### Check 81/2008

---

|                                       |  |
|---------------------------------------|--|
| ◆ Condizioni freni:                   | Molto Buono                            |
| ◆ Condizioni freno di Stazionamento:  | Molto Buono                            |
| ◆ Glass conditions:                   | Excellent - no needs repair            |
| ◆ Lights conditions:                  | Excellent - no needs repair            |
| ◆ Condizioni specchietti:             | Eccellente - non necessita riparazione |
| ◆ Stepladders & handrails conditions: | Very good                              |
| ◆ Cameras conditions:                 | Excellent - no needs repair            |
| ◆ Flashing conditions:                | Present and functioning                |
| ◆ Safety belt conditions:             | Present and valid                      |

---

|  |                         |
|--|-------------------------|
| ◆ Controls been modified:                        | No                      |
| ◆ Presence of Exclusion Control Lever:           | Yes                     |
| ◆ Are Tools Functional & Visible with tag:       | Yes                     |
| ◆ Canopy completed and comes with keys and bolt: | Yes                     |
| ◆ All Pipes with no damage e/o scratches:        | Yes                     |
| ◆ Batteries box shielded:                        | Yes                     |
| ◆ Acoustic alarm works properly:                 | Yes                     |
| ◆ Boardwalk presence:                            | Present and functioning |

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.