

## SALES REPORT: CATERPILLAR M316D - SN W6A05### - Year 2010

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

### MACHINE DATA

---

**Model:** M316D

**Family:** WHEEL EXCAVATOR

**Serial Number:** W6A05###

**Order Number MU/MM:** MU00828092

**Construction year:** 2010

**Hour meter:** 13900

**General residual conditions Truck/Tyres:** 70 %

**Machine main application:** Basic application

**Machine availability date :** 27/05/2026

**Location:** Coming in

**Rating:** ★★☆☆☆

**Public price:** 56.000 €

### MACHINE CONFIGURATION

---

• Machine type Standard • Boom type Triple boom • Boom check valves • Stick check valves • Plant features Versatility • Quick coupler Mechanic MARCA VTN - MOD. 11EY65 • Bucket / Grapple Standard Get Cover Blade 1200 • Tyres type Twin Wheel • General Tyres Residual 70 10.00-20 ASCENSO • Blade • Stabilizers 2 Stabilizers • Cabin type Fixed standard • Air Conditioning system Operation Yes • Product Link • 17850 Kg • CE Mark • CE Certificate • Use and maintenance manual • Registration book & Licence plate Registration book & Licence plate AHX643

**MACHINE PHOTOS**

---

◆ Il contaore e':

Funzionante











**GENERAL APPEARANCE**

---

- ◆ Painting Conditions Good

---

- ◆ Counterweight conditions Good

---

- Needs painting? : No

---

- ◆ Frame / Bumper conditions Good

---

**Tyres**

---

- ◆ Front Tyres residual 70

---

- ◆ Front Tyres residual 69

---

**Right side**

---

- ◆ Door conditions (right) Good

---

- ◆ Spar conditions (right) Good

---

**Left side**

---

- ◆ Door conditions (left) Good

---

- ◆ Door conditions (left) Good

---

- ◆ Spar conditions (left) Good

---

- ◆ Hood / Armor bottom conditions Present and intact

---

**Functionality**

---

### Engine & electrical system functionality

---

◆ In quale stato è stata visionata la macchina:	Accesa e provata per ispezione
<hr/>	
◆ Engine functionality conditions	Good
<hr/>	
◆ Engine with oil leaks	No
<hr/>	
◆ Engine presents blowby	No
<hr/>	
◆ Oil-Water presence	No
<hr/>	
◆ Engine present smokiness	No
<hr/>	
◆ Radiator conditions	Good
<hr/>	
◆ Starter motor conditions	Good
<hr/>	
◆ Batteries/Cables conditions	Good
<hr/>	
◆ Presence of electrical fault	No
<hr/>	

### Functionality drive and rotation

---

◆ Hydraulic pump conditions	Good
<hr/>	
◆ Engine rotation conditions	Good
<hr/>	
◆ Engine travel conditions	Good
<hr/>	
◆ Final drives conditions	Good
<hr/>	
◆ Hydraulic joint conditions	Good
	Presence of leaks : No
<hr/>	
◆ Hydraulic joint conditions	Good
	Presence of leaks : No
<hr/>	

◆ Tenuta idraulica braccio (il braccio cala): No

---

### Linkage Group

---

◆ Hydraulic conditions linkage group (Boom is lowering?) Yes

---

◆ Boom structure Good

Presence of welding/cracks : No

---

◆ Stick structure Good

Presence of welding/cracks : No

---

◆ Flexible pipes conditions Good

---

◆ Boom cylinders conditions Good

Leaks : No

---

◆ Stick cylinder conditions Good

Leaks : No

---

◆ Bucket / Grapple cylinder conditions Good

Leaks : No

---

◆ Pins & Bushings boom conditions Good

---

◆ Pins & Bushings stick conditions Good

---

◆ Pins & Bushings bucket conditions Good

---

◆ Bucket / Grapple & Get conditions Good

---

◆ Quick Coupler conditions Good

---

◆ Funzionamento Impianto Ingrassaggio Automatico: No

---

### Cabin and Tools

---

◆ Conditions internal cabin	Good
◆ Flashing presents issues	Yes
◆ Lights & Windshield present issues	Presents and functioning
◆ Air contidioning & Filters conditions	Presents and functioning
◆ Back & side camera conditions	Present and functioning

### Check 81/2008

◆ Condizioni freni:	Buono
◆ Condizioni freno di Stazionamento:	Buono
◆ Glass conditions	Excellent - no needs repair
◆ Lights conditions	Excellent - no needs repair
◆ Rear view mirrors conditions	Excellent - no needs repair
◆ Stepladders & handrails conditions	Good
◆ Cameras conditions	Excellent - no needs repair
◆ Flashing conditions	Present and functioning
◆ Safety belt conditions	Present and expired
◆ Controls been modified	No
◆ Presence of Exclusion Control Lever	Yes
◆ Are Tools Functional & Visible with tag	Yes
◆ Canopy completed and comes with keys and bolt	Yes
◆ All Pipes with no damage e/o scratches	Yes

---

◆ Batteries box shielded	Yes
◆ Acoustic alarm works properly	Yes
◆ Boardwalk presence	Present and functioning

---

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.