

SALES REPORT: CATERPILLAR MH3024 - SN FB700### - Year 2018

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: MH3024

Family: WHEEL EXCAVATOR

Serial Number: FB700###

Order Number MU/MM: MU00829242

Construction year: 2018

Hour meter: 16510

General residual conditions Truck/Tyres: 5 %

Machine main application: Landfill

Machine availability date : 01/07/2026

Location: Coming in

Rating: ★★☆☆☆

Public price: Ask

MACHINE CONFIGURATION

- Machine type Material Handling MH
- Boom type Mono boom
- Boom check valves
- Stick check valves
- Plant features Versatility
- Bucket / Grapple Grapple
- Tyres type Twin Wheel
- General Tyres Residual 5 10.00-20 Globe Star NO POLIPO; lama con deformazioni; Pneumatici Con segni, usure varie;
- Blade
- Stabilizers 4
- Cabin type Hydraulic lift
- Cabin fog Front superiore
- Air Conditioning system Operation Yes
- Auto lube system Operation Yes
- Product Link
- 1 Kg
- CE Mark
- CE Certificate
- Use and maintenance manual
- Registration book & Licence plate No Registration book & Licence plate
- AVAILABLE FROM JULY

MACHINE PHOTOS

◆ Il contaore e':

Funzionante











GENERAL APPEARANCE

◆ Painting Conditions	Poor
◆ Counterweight conditions	Poor
	Needs painting? : Yes
◆ Frame / Bumper conditions	Poor

Tyres

◆ N/D 5

◆ N/D 5

Right side

◆ N/D Poor

◆ N/D Poor

◆ N/D segni, strusciature, ammaccature

Left side

◆ N/D Poor

◆ N/D Poor

◆ N/D Poor

◆ N/D segni, strusciature, ammaccature; crinature

◆ Hood / Armor bottom conditions Present and bash

Functionality

Engine & electrical system functionality

◆ N/D Accesa e funzionante "al lavoro"

◆ N/D Good

◆ N/D No

If Yes, where : trasudi

◆ N/D	No
◆ N/D	No
◆ N/D	No
◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ N/D	No

Functionality drive and rotation

◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
	Presence of leaks : No
◆ N/D	Good
	Presence of leaks : No
◆ N/D	No

Linkage Group

◆ N/D	Yes
-------	-----

◆ N/D	Very good
	Presence of welding/cracks : No
◆ N/D	Poor
	Presence of welding/cracks : No
◆ N/D	Poor
◆ N/D	Good
	Leaks : No
◆ N/D	Good
	Leaks : No
◆ N/D	NA - Not applicable
	Leaks : No
◆ N/D	Good
◆ N/D	Good
◆ N/D	NA - Not applicable
◆ N/D	NA - Not applicable
◆ N/D	NA - Not applicable
◆ N/D	Si
◆ N/D	NO POLIPO; Trasudi idraulici; Giochi compatibili con le ore/applicazione; Braccio boom sostituito 2025/2026; Riduttore rotazione sostituito 2026; Da spessorare braccio boom attacco stick (rumorosità in fase di rotazione);

Cabin and Tools

◆ Conditions internal cabin	Poor
	Other notes : Sistema di pesatura Vei; copri pulsanti manipolatori usurati rotti;
◆ Flashing presents issues	No

◆ Lights & Windshield present issues Presents and functioning

◆ Air conditioning & Filters conditions Presents and functioning

◆ Back & side camera conditions Present and functioning

Check 81/2008

◆ Condizioni freni: Scarso

◆ Condizioni freno di Stazionamento: Buono

◆ Glass conditions Broken or Chipped - needs repair

◆ Lights conditions Broken or Chipped - needs repair

◆ Rear view mirrors conditions Broken or Chipped - needs repair

◆ Stepladders & handrails conditions Poor

◆ Cameras conditions Excellent - no needs repair

◆ Flashing conditions Not functioning

◆ Safety belt conditions Present and valid

◆ Controls been modified No

◆ Presence of Exclusion Control Lever Yes

◆ Are Tools Functional & Visible with tag Yes

◆ Canopy completed and comes with keys and bolt No

◆ All Pipes with no damage e/o scratches No

◆ Batteries box shielded Yes

◆ Acoustic alarm works properly Yes

◆ Boardwalk presence

Not present

◆ Annotazioni su

Freni funzionanti; Accumulatore Pilota scarico (da sostituire);

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.