

SALES REPORT: CATERPILLAR 303 E CR - SN SGE01175 - Year 2020

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: 303 E CR

Family: MINI EXCAVATOR

Serial Number: SGE01175

Order Number MU/MM: MU00829483

Construction year: 2020

Hour meter: 2212

General residual conditions Truck/Tyres: 70 %

Machine main application: Basic application

Location: Stock Bianchin Elevazi

Rating: ★★☆☆☆

Public price: Ask

MACHINE CONFIGURATION

- Machine type Standard
- Boom type Mono boom
- Boom check valves
- Stick check valves
- Plant features Hammer line impianto combinato
- Quick coupler Mechanic
- Bucket Standard 400 Get Teeth 1
- Truck type Fixed
- Blade
- General Truck Residual 70%
- Cabin type Fixed standard
- 3140 Kg
- CE Mark
- CE Certificate
- EPA Tag
- Use and maintenance manual

MACHINE PHOTOS

◆ Il contaore è:

Sostituito







GENERAL APPEARANCE

| | |
|-----------------------------|------|
| ◆ Painting Conditions | Good |
| ◆ Counterweight conditions: | Good |
| ◆ Frame/Bumper conditions: | Good |

TRUCK

| | |
|-------|----|
| ◆ N/D | 70 |
| ◆ N/D | 70 |
| ◆ N/D | 70 |
| ◆ N/D | 40 |

Right side

| | |
|-------|------|
| ◆ N/D | Good |
| ◆ N/D | Good |

Left side

| | |
|---------------------------------|------------------|
| ◆ N/D | Good |
| ◆ N/D | Good |
| ◆ N/D | Good |
| ◆ Hood/Armor bottom conditions: | Present and bash |

Functionality

Engine & electrical system functionality

| | |
|-------|--------------------------------|
| ◆ N/D | Accesa e provata per ispezione |
| ◆ N/D | Good |
| ◆ N/D | No |
| ◆ N/D | No |
| ◆ N/D | No |
| ◆ N/D | No |
| ◆ N/D | Good |
| ◆ N/D | Good |
| ◆ N/D | Good |
| ◆ N/D | No |

Functionality drive and rotation

| | |
|-------|------|
| ◆ N/D | Good |
| ◆ N/D | Good |
| ◆ N/D | Good |
| ◆ N/D | Good |
| ◆ N/D | Good |

Presence of leaks : No

◆ N/D Good
Presence of leaks : No

Linkage Group

◆ N/D No

◆ N/D Good
Presence of welding/cracks : No

◆ N/D Good
Presence of welding/cracks : No

◆ N/D Good

◆ N/D Good
Leaks : No

◆ N/D Good
Leaks : No

◆ N/D Good
Leaks : No

◆ N/D Good

◆ N/D Good

◆ N/D Poor

◆ N/D Good

◆ N/D Good

◆ N/D No

Cabin and Tools

| | |
|---------------------------------------|--------------------------|
| ◆ Conditions internal cabin: | Good |
| ◆ Flashing presents issues: | No |
| ◆ Lights & Windshield present issues: | Presents and functioning |
| ◆ Air conditioning is working: | Non Presente |
| ◆ Back & side camera conditions: | Not functioning |

Check 81/2008

| | |
|--|----------------------------------|
| ◆ Glass conditions: | Excellent - no needs repair |
| ◆ Lights conditions: | Excellent - no needs repair |
| ◆ Rear view mirrors conditions: | Excellent - no needs repair |
| ◆ Stepladders & handrails conditions: | Good |
| ◆ Cameras conditions: | Broken or Chipped - needs repair |
| ◆ Flashing conditions: | Not functioning |
| ◆ Safety belt conditions: | Present and expired |
| ◆ Controls been modified: | No |
| ◆ Presence of Exclusion Control Lever: | Yes |
| ◆ Are Tools Functional & Visible with tag: | Yes |
| ◆ Canopy completed and comes with keys and bolt: | Yes |
| ◆ All Pipes with no damage e/o scratches: | Yes |
| ◆ Batteries box shielded: | Yes |
| ◆ Acoustic alarm works properly: | Yes |

◆ Boardwalk presence:

Not present

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.