

SALES REPORT: JCB JS190#KJCB - SN 1224002 - Year 2006

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: JS190#KJCB

Family: SMALL EXCAVATOR

Serial Number: 1224002

Order Number MU/MM: MU00832321

Construction year: 2006

Hour meter: 10169

General residual conditions Truck/Tyres: 29 %

Machine main application: Basic application

Location: Stock Villa Autotrasp

Rating: ★★☆☆☆

Public price: 21.000 €


MACHINE CONFIGURATION

• Machine type Standard • Boom type Triple boom • Boom check valves • Stick check valves • Bucket Standard 1400 mm Get Teeth benna p/f mm 1800, scavo mm 600 • Truck type Fixed • General Truck Residual 29% • Cabin type Fixed standard • 20431 Kg

MACHINE PHOTOS

◆ Il contaore è:

Funzionante











GENERAL APPEARANCE

◆ Painting Conditions	Poor
◆ Counterweight conditions:	Poor
◆ Frame/Bumper conditions:	Poor

TRUCK

◆ N/D	29
◆ N/D	29
◆ N/D	29
◆ N/D	28

Right side

◆ N/D	Poor
◆ N/D	Poor

Left side

◆ N/D	Poor
◆ N/D	Poor
◆ N/D	Poor
◆ Hood/Armor bottom conditions:	Present and bash

Functionality

Engine & electrical system functionality

◆ N/D	Accesa e provata per ispezione
◆ N/D	Poor
◆ N/D	Yes
	If Yes, where : varie
◆ N/D	No
◆ N/D	No
◆ N/D	No
◆ N/D	Poor

◆ N/D		Poor
-------	--	------

◆ N/D		Poor
-------	--	------

◆ N/D		Sì
-------	--	----

SE SI, AGGIUNGERE DETTAGLI : spia generica, manutenzione da eseguire

Functionality drive and rotation

◆ N/D		Poor
-------	--	------

◆ N/D		Poor
-------	--	------

◆ N/D		Poor
-------	--	------

◆ N/D		Poor
-------	--	------

◆ N/D		Poor
-------	--	------

Presence of leaks : No

◆ N/D		Poor
-------	--	------

Presence of leaks : Yes

Linkage Group

◆ N/D		No
-------	--	----

◆ N/D		Good
-------	--	------

Presence of welding/cracks : No

◆ N/D		Poor
-------	--	------

Presence of welding/cracks : No

◆ N/D		Poor
-------	--	------

◆ N/D		Poor
-------	--	------

Leaks : Yes

◆ N/D	Poor
	Leaks : Yes
◆ N/D	Poor
	Leaks : No
◆ N/D	Poor
◆ N/D	Poor
◆ N/D	Poor
◆ N/D	Poor
◆ N/D	NA - Not applicable
◆ N/D	No

Cabin and Tools

◆ Conditions internal cabin:	Poor
◆ Flashing presents issues:	No
◆ Lights & Windshield present issues:	Not presents
◆ Air conditioning is working:	Non Presente
◆ Back & side camera conditions:	Not functioning

Check 81/2008

◆ Glass conditions:	Broken or Chipped - needs repair
◆ Lights conditions:	Broken or Chipped - needs repair
◆ Rear view mirrors conditions:	Mancanti

◆ Stepladders & handrails conditions:	Poor
◆ Cameras conditions:	Broken or Chipped - needs repair
◆ Flashing conditions:	Not functioning
◆ Safety belt conditions:	Not present/Broken
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	No
◆ Canopy completed and comes with keys and bolt:	No
◆ All Pipes with no damage e/o scratches:	No
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	No
◆ Boardwalk presence:	Present and bashee
◆ Annotazioni su:	arresto motore non funzionante, si spegne con un cavi nel vano motore.

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.