

SALES REPORT: CATERPILLAR 962M - SN JYD20### - Year 2020

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: 962M

Family: MEDIUM WHEEL LOADER

Serial Number: JYD20###

Order Number MU/MM: MU00833252

Construction year: 2020

Hour meter: 11989

General residual conditions Truck/Tyres: 90 %

Machine main application: Basic application

Machine availability date : 01/07/2026

Location: Coming in

Rating: ★★☆☆☆

Public price: Ask

MACHINE CONFIGURATION

● Machine type Standard - GP ● Steering type Joystick ● Differential Type Standard ● Transmission type Automatic ● Ride Control ● Bucket Standard Get Cover Blade ● Tyres type Standard ● General Tyres Residual 90 ● Rops Close ● Air Conditioning system ● Weight Scale ● Product Link ● 20200 Kg ● CE Mark ● CE Certificate ● EPA Tag ● Use and maintenance manual ● Registration book & Licence plate undefined ● AVAILABLE FROM JULY

MACHINE PHOTOS

◆ Il contaore e':

Funzionante















GENERAL APPEARANCE

- ◆ Painting Conditions: Very Good

- ◆ Counterweight conditions: Very good
Needs painting? : No

- ◆ Frame/Bumper conditions: Very Good

- ◆ Door conditions: Very good

- ◆ Central joint: Very good

- ◆ Fender/Mudguard conditions: Very good

- ◆ Other notes: Griglia radiatore post leggermente ammaccata

Tyres

◆	N/D	70
---	-----	----

◆	N/D	70
---	-----	----

Functionality

Engine & electrical system functionality

◆	N/D	Accesa e funzionante "al lavoro"
---	-----	----------------------------------

◆	N/D	Very good
---	-----	-----------

◆	N/D	No
---	-----	----

◆	N/D	No
---	-----	----

◆	N/D	No
---	-----	----

◆	N/D	No
---	-----	----

◆	N/D	Very good
---	-----	-----------

◆	N/D	Very good
---	-----	-----------

◆	N/D	Very good
---	-----	-----------

◆	N/D	No
---	-----	----

Functionality drive and rotation

◆	N/D	Very good
---	-----	-----------

◆	N/D	Very good
---	-----	-----------

◆	N/D	Very good
---	-----	-----------

◆ N/D Very good

Presence of leaks : No

◆ N/D Very Good

Engine & electrical system functionality

◆ N/D Very good

◆ N/D Very good

◆ N/D Very good

Linkage Group

◆ N/D No

◆ N/D Very good

Presence of welding/cracks : No

◆ N/D Very good

◆ N/D Very good

◆ N/D Very good

◆ N/D Very good

◆ N/D Very good

◆ N/D NA - Not applicable

◆ N/D No

Cabin and Tools

◆ Conditions internal cabin:	Very good
◆ Lights & Windshield present issues:	Presents and functioning
◆ Air contidioning & Filters conditions:	Presents and functioning
◆ Back & side camera conditions:	Present and functioning

Check 81/2008

◆ Condizioni freni:	Molto Buono
◆ Condizioni freno di Stazionamento:	Molto Buono
◆ Glass conditions:	Excellent - no needs repair
◆ Lights conditions:	Excellent - no needs repair
◆ Condizioni specchietti:	Eccellente - non necessita riparazione
◆ Stepladders & handrails conditions:	Very good
◆ Cameras conditions:	Excellent - no needs repair
◆ Flashing conditions:	Present and functioning
◆ Safety belt conditions:	Present and valid
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes

◆ Acoustic alarm works properly: Yes

◆ Boardwalk presence: Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.