

SALES REPORT: CATERPILLAR AP300 - SN B2Y00### - Year 2010

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: AP300

Family: ASPHALT PAVERS

Serial Number: B2Y00###

Order Number MU/MM: MU00834182

Construction year: 2010

Hour meter: 4619

General residual conditions Truck/Tyres: %

Machine main application:

Machine availability date : 23/06/2026

Location: Coming in

Rating: ★★☆☆☆


Public price: Ask



MACHINE CONFIGURATION

● Machine type Mass Excavator ● Boom type ● Boom check valves ● Truck type ● Product Link undefined non riscaldate ● EPA Tag ● ● 7300 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual Livellazione non presente ● AVAILABLE FROM AUGUST

MACHINE PHOTOS











GENERAL APPEARANCE

◆ Painting Conditions	Good
◆ Spar conditions:	Good
◆ Residual % - Tyres/Track:	50
◆ Residual % - Cushion:	50
◆ Seat condition:	Good
◆ Engine working conditions:	Good
◆ Radiator conditions:	Good
◆ Batteries/Cables conditions:	Good

Functionality

SCREED

◆ N/D	1800-3200
◆ N/D	30
◆ N/D	1
◆ N/D	50
◆ N/D	50
◆ N/D	30
◆ N/D	300

Engine & electrical system functionality

◆ N/D	Accesa e provata per ispezione
◆ N/D	Good
◆ N/D	No
◆ N/D	No
◆ N/D	No
◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ N/D	No

Functionality drive and rotation

◆ N/D	Good
◆ N/D	Good
◆ N/D	Good

Linkage Group

◆ N/D	Good	Presenza di perdite? Se si, specificare da dove: : No
◆ N/D	Good	Presenza di perdite? Se si, specificare da dove: : No
◆ N/D	Good	Presenza di perdite? Se si, specificare da dove: : No
◆ N/D	NA - Not applicable	

Check 81/2008

◆ Condizioni freni:	Buono
◆ Condizioni freno di Stazionamento:	Buono
◆ Lights conditions:	Excellent - no needs repair
◆ Condizioni specchietti:	Rotto o Scheggiato - necessita riparazione
◆ Stepladders & handrails conditions:	Good
◆ Cameras conditions:	Broken or Chipped - needs repair

◆ Flashing conditions:	Present and functioning
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	No
If No, are control levers protected to accidental functionality? : No	
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	No
◆ Boardwalk presence:	Not present
◆ Annotazioni su:	Console sul banco non fotografate ma funzionanti ed in discrete condizioni

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.