

## SALES REPORT: CATERPILLAR 304 E2 - SN ME409634 - Year 2021

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

### MACHINE DATA

---

**Model:** 304 E2

**Family:** MINI EXCAVATOR

**Serial Number:** ME409634

**Order Number MU/MM:** MU00834255

**Construction year:** 2021

**Hour meter:** 507

**General residual conditions Truck/Tyres:** 90 %

**Machine main application:** Basic application

**Location:** Stock Off.Buniotto

**Rating:** ★★☆☆☆

**Public price:** Ask

### MACHINE CONFIGURATION

---

- Machine type Standard
- Boom type Mono boom
- Boom check valves
- Plant features Versatility
- Quick coupler Mechanic CR
- Bucket Standard 30 CM Get Teeth 3 BENNE
- Truck type Fixed
- Blade
- General Truck Residual 85%
- Cabin type Fixed standard
- Air Conditioning system
- Product Link
- Antitheft alarm
- 4500 Kg
- CE Mark
- CE Certificate
- EPA Tag
- Use and maintenance manual

## MACHINE PHOTOS

---

◆ Il contaore è:

Funzionante















**GENERAL APPEARANCE**

---

- ◆ Painting Conditions Good

---

- ◆ Counterweight conditions: Good

---

- ◆ Frame/Bumper conditions: Very Good

---

**TRUCK**

---

- ◆ N/D 85

---

- ◆ N/D 85

---

◆ N/D 85

---

◆ N/D 85

---

**Right side**

---

◆ N/D Good

---

◆ N/D Very good

---

**Left side**

---

◆ N/D Good

---

◆ N/D Very good

---

◆ N/D Very good

---

◆ Hood/Armor bottom conditions: Present and intact

---

**Functionality**

---

**Engine & electrical system functionality**

---

◆ N/D Accesa e provata per ispezione

---

◆ N/D Good

---

◆ N/D No

---

◆ N/D No

---

◆ N/D No

---

◆ N/D No

◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ N/D	No

**Functionality drive and rotation**

◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
	Presence of leaks : No
◆ N/D	Good
	Presence of leaks : No

**Linkage Group**

◆ N/D	No
◆ N/D	Very good
	Presence of welding/cracks : No
◆ N/D	Good
	Presence of welding/cracks : No
◆ N/D	Good
◆ N/D	Good

	Leaks : No
◆ N/D	Good
	Leaks : No
◆ N/D	Good
	Leaks : No
◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ N/D	No

**Cabin and Tools**

---

◆ Conditions internal cabin:	Good
◆ Flashing presents issues:	No
◆ Lights & Windshield present issues:	Presents and functioning
◆ Air conditioning is working:	Presente e funzionante
◆ Back & side camera conditions:	Not functioning

**Check 81/2008**

---

◆ Glass conditions:	Excellent - no needs repair
◆ Lights conditions:	Excellent - no needs repair

---

◆ Rear view mirrors conditions:	Excellent - no needs repair
◆ Stepladders & handrails conditions:	Good
◆ Cameras conditions:	Broken or Chipped - needs repair
◆ Flashing conditions:	Not functioning
◆ Safety belt conditions:	Present and valid
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	Yes
◆ Boardwalk presence:	Present and functioning

---

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.