

## SALES REPORT: CATERPILLAR 259D3 - SN TE900798 - Year 2021

This Report is a summary about observations came out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

### MACHINE DATA

---

**Model:** 259D3

**Family:** COMPACT TRACK LOADER

**Serial Number:** TE900798

**Order Number MU/MM:** MU00834982

**Construction year:** 2021

**Hour meter:** 324

**General residual conditions Truck/Tyres:** 90 %

**Machine main application:** Basic application

**Location:** Stock Off.Buniotto

**Rating:** ★★☆☆☆

**Public price:** Ask

### MACHINE CONFIGURATION

---

● Machine type Wasting configuration ● Rops Close ● Bucket Standard 0,33 Get Get ● Plant features ● General Truck Residual 90% ● Air Conditioning system ● Product Link ● Antitheft alarm ● ● CE Mark ● CE Certificate ● EPA Tag ● Use and maintenance manual ● undefined

## MACHINE PHOTOS

---

◆ Il contaore e': Funzionante

---

## GENERAL APPEARANCE

---

◆ Painting Conditions Good

---

◆ Counterweight conditions Good  
Needs painting? : No

---

◆ Frame/Bumper conditions Good

---

◆ Door conditions (left) Good

---

### Truck

---

◆ N/D 90

---

◆ N/D 90

---

◆ N/D 90

---

◆ N/D 40

---

◆ N/D 40

---

## Functionality

---

### Engine & electrical system functionality

---

◆ N/D Accesa e provata per ispezione

---

◆ N/D Good

---

◆ N/D No

---

◆ N/D No

---

◆ N/D No

---

◆ N/D No

---

◆ N/D Good

---

◆ N/D Good

---

◆ N/D Good

---

◆ N/D No

---

**Functionality drive and rotation**

---

◆ N/D Good

---

◆ N/D Good

---

◆ N/D Good

---

◆ N/D Good

---

**Linkage Group**

---

◆ N/D No

---

◆ N/D Good

---

Presence of welding/cracks : No

---

◆ N/D Good

---

◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ N/D	No

### Cabin and Tools

---

◆ Conditions internal cabin:	Good
◆ Lights & Windshield present issues_	Presents and functioning
◆ Air contidioning & Filters conditions:	Presents and functioning
◆ Back & side camera conditions:	Present and functioning

### Check 81/2008

---

◆ Glasses conditions:	Excellent - no needs repair
◆ Lights conditions:	Excellent - no needs repair
◆ Condizioni specchietti:	Eccellente - non necessita riparazione
◆ Stepladders & handrails conditions:	Excellent
◆ Cameras conditions:	Excellent - no needs repair
◆ Flashing conditions:	Present and functioning
◆ Safety belt conditions:	Present and valid

◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	Yes
◆ Boardwalk presence:	Present and functioning

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.