

SALES REPORT: CASE SR160#KCASE - SN NLM481### - Year 2020

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: SR160#KCASE

Family: SKID STEER LOADER

Serial Number: NLM481###

Order Number MU/MM: MU00836204

Construction year: 2020

Hour meter: 1300

General residual conditions Truck/Tyres: 90 %

Machine main application: Basic application

Machine availability date : 01/08/2026

Location: Coming in

Rating: ★★☆☆☆

Public price: Ask

MACHINE CONFIGURATION

● Machine type Standard - GP ● Rops Open ● Bucket Bucket 4 in 1 - Multi Purpose BENNA 4 in 1 NUOVA ● General Truck Residual 90% ● 2300 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual ● undefined

MACHINE PHOTOS

◆ Il contaore e':

Funzionante







GENERAL APPEARANCE

◆ Painting Conditions	Very Good
◆ Counterweight conditions	NA - Not applicable
	Needs painting? : No
◆ Frame/Bumper conditions	Very Good
◆ Door conditions (left)	Very good

Truck

◆ N/D	70
◆ N/D	70

Functionality

Engine & electrical system functionality

◆ N/D	Accesa e funzionante "al lavoro"
◆ N/D	Very good
◆ N/D	No
◆ N/D	No
◆ N/D	No
◆ N/D	No
◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ N/D	No

Functionality drive and rotation

◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ N/D	Good

Linkage Group

◆ N/D	No
◆ N/D	Good
	Presence of welding/cracks : No
◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ N/D	No

Cabin and Tools

◆ Conditions internal cabin:	Good
◆ Lights & Windshield present issues_	Presents and functioning
◆ Air contidioning & Filters conditions:	Not functioning
◆ Back & side camera conditions:	Not functioning

Check 81/2008

◆ Glasses conditions:	Excellent - no needs repair
◆ Lights conditions:	Excellent - no needs repair
◆ Condizioni specchietti:	Eccellente - non necessita riparazione

- ◆ Stepladders & handrails conditions: Good

- ◆ Cameras conditions: Non presente

- ◆ Flashing conditions: Present and functioning

- ◆ Safety belt conditions: Present and expired

- ◆ Controls been modified: No

- ◆ Presence of Exclusion Control Lever: Yes
If No, are control levers protected to accidental functionality? : Yes

- ◆ Are Tools Functional & Visible with tag: Yes

- ◆ Canopy completed and comes with keys and bolt: Yes

- ◆ All Pipes with no damage e/o scratches: Yes

- ◆ Batteries box shielded: Yes

- ◆ Acustic alarm works properly: Yes

- ◆ Boardwalk presence: Not present

- ◆ Annotazioni su: TAGLIANDO ESEGUITO DA 50 ORE

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.