

SALES REPORT: CATERPILLAR M315F - SN F4D00548 - Year 2017

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: M315F

Family: WHEEL EXCAVATOR

Serial Number: F4D00548

Order Number MU/MM: MU00836997

Construction year: 2017

Hour meter: 5201

General residual conditions Truck/Tyres: 40 %

Machine main application: Basic application

Location: Stock Brescia

Rating: ★★☆☆☆

Public price: 86.500 €

MACHINE CONFIGURATION


• Machine type Standard • Boom type Parallelogramm • Boom check valves • Stick check valves • Plant features Versatility impianto dedicato all'attacco rapido • Quick coupler Hydraulic Cw20s • Tyres type Twin Wheel • General Tyres Residual 40 10.00-20 Bkt • Blade • Stabilizers No Stabilizers • Cabin type Fixed standard • Air Conditioning system Operation Yes • Auto lube system Operation Yes • Product Link • Antitheft alarm • 16500Kg • CE Mark • CE Certificate • EPA Tag • Use and maintenance manual • Registration book & Licence plate Registration book & Licence plate AKW906

MACHINE PHOTOS

◆ Il contaore e':


Funzionante



















GENERAL APPEARANCE

Painting Conditions	Excellent
Counterweight conditions	Excellent
	Needs painting? : No
Frame / Bumper conditions	Excellent

Tyres

N/D	40
N/D	40

Right side

N/D	Excellent
---	-----------

◆ N/D	Excellent
-------	-----------

Left side

◆ N/D	Excellent
-------	-----------

◆ N/D	Excellent
-------	-----------

◆ N/D	Excellent
-------	-----------

◆ Hood / Armor bottom conditions	Present and intact
----------------------------------	--------------------

Functionality

Engine & electrical system functionality

◆ N/D	Accesa e funzionante "al lavoro"
-------	----------------------------------

◆ N/D	Very good
-------	-----------

◆ N/D	No
-------	----

◆ N/D	No
-------	----

◆ N/D	No
-------	----

◆ N/D	No
-------	----

◆ N/D	Very good
-------	-----------

◆ N/D	Very good
-------	-----------

◆ N/D	Very good
-------	-----------

◆ N/D	No
-------	----

Functionality drive and rotation

◆ N/D	Very good
◆ N/D	Very good
◆ N/D	Very good
◆ N/D	Very good
◆ N/D	Very good
	Presence of leaks : No
◆ N/D	Very good
	Presence of leaks : No
◆ N/D	No

Linkage Group

◆ N/D	Yes
◆ N/D	Excellent
	Presence of welding/cracks : No
◆ N/D	Very good
	Presence of welding/cracks : No
◆ N/D	Very good
◆ N/D	Very good
	Leaks : No
◆ N/D	Very good
	Leaks : No
◆ N/D	Very good

	Leaks : No
◆ N/D	Very good
◆ N/D	Very good
◆ N/D	Very good
◆ N/D	NA - Not applicable
◆ N/D	Very good
◆ N/D	Sì

Cabin and Tools

◆ Conditions internal cabin	Very good
Other notes : Macchina completa di predisposizione sistema 3d Tranne supporto monitor cabina	
◆ Flashing presents issues	Yes
◆ Lights & Windshield present issues	Presents and functioning
◆ Air contidioning & Filters conditions	Presents and functioning
◆ Back & side camera conditions	Present and functioning

Check 81/2008

◆ Condizioni freni:	Molto Buono
◆ Condizioni freno di Stazionamento:	Molto Buono
◆ Glass conditions	Excellent - no needs repair
◆ Lights conditions	Excellent - no needs repair

◆ Rear view mirrors conditions	Broken or Chipped - needs repair
◆ Stepladders & handrails conditions	Very good
◆ Cameras conditions	Excellent - no needs repair
◆ Flashing conditions	Present and functioning
◆ Safety belt conditions	Present and expired
◆ Controls been modified	Yes
◆ Presence of Exclusion Control Lever	Yes
If No, are control levers protected to accidental functionality? : No	
◆ Are Tools Functional & Visible with tag	Yes
◆ Canopy completed and comes with keys and bolt	Yes
◆ All Pipes with no damage e/o scratches	Yes
◆ Batteries box shielded	Yes
◆ Acoustic alarm works properly	Yes
◆ Boardwalk presence	Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.