

SALES REPORT: CASE 721G - SN GNZHE14### - Year 2022

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: 721G

Family: MEDIUM WHEEL LOADER

Serial Number: GNZHE14###

Order Number MU/MM: MU00837066

Construction year: 2022

Hour meter: 6547

General residual conditions Truck/Tyres: 60 %

Machine main application: Industry - not corrosive field

Machine availability date : 01/08/2026

Location: Coming in

Rating: ★★☆☆☆

Public price: 125.000 €

MACHINE CONFIGURATION

• Machine type Standard - GP • Steering type Command steering Presence of Command Steering Yes • Differential Type Self-Locking • Transmission type Manual • Auxiliary Systems • Quick Coupler System • Bucket Ditch Cleaning Bucket materiali leggeri Leonardi Benne 4,1mc / 2750 Get Cover Blade • Tyres type Rock • General Tyres Residual 60 23.5R25 Bridgestone • Rops Close • Air Conditioning system • Weight Scale • 15700 Kg • CE Mark • CE Certificate • Use and maintenance manual • Registration book & Licence plate undefined


MACHINE PHOTOS

◆ Il contaore e':


Funzionante














GENERAL APPEARANCE

◆ Painting Conditions:	Very Good
◆ Counterweight conditions:	Very good
	Needs painting? : No
◆ Frame/Bumper conditions:	Very Good
◆ Door conditions:	Very good
◆ Central joint:	Very good
◆ Fender/Mudguard conditions:	Very good

Tyres

◆ N/D

◆ N/D		70
-------	--	----

Functionality

Engine & electrical system functionality

◆ N/D	Accesa e funzionante "al lavoro"	
-------	----------------------------------	--

◆ N/D		Very good
-------	--	-----------

◆ N/D		No
-------	--	----

◆ N/D		No
-------	--	----

◆ N/D		No
-------	--	----

◆ N/D		No
-------	--	----

◆ N/D		Good
-------	--	------

◆ N/D		Good
-------	--	------

◆ N/D		Good
-------	--	------

◆ N/D		No
-------	--	----

Functionality drive and rotation

◆ N/D		Good
-------	--	------

◆ N/D	NA - Not applicable	
-------	---------------------	--

◆ N/D	NA - Not applicable	
-------	---------------------	--

◆ N/D		Good
-------	--	------

Presence of leaks : No

◆ N/D Good

Engine & electrical system functionality

◆ N/D Very good

◆ N/D Good

◆ N/D Good

Linkage Group

◆ N/D No

◆ N/D Good

Presence of welding/cracks : No

◆ N/D Good

◆ N/D Good

◆ N/D Good

◆ N/D Good

◆ N/D Good

◆ N/D NA - Not applicable

◆ N/D No

Cabin and Tools

◆ Conditions internal cabin: Very good

◆ Lights & Windshield present issues:	Presents and functioning
◆ Air conditioning & Filters conditions:	Presents and functioning
◆ Back & side camera conditions:	Present and functioning

Check 81/2008

◆ Condizioni freni:	Buono
◆ Condizioni freno di Stazionamento:	Buono
◆ Glass conditions:	Excellent - no needs repair
◆ Lights conditions:	Excellent - no needs repair
◆ Condizioni specchietti:	Eccellente - non necessita riparazione
◆ Stepladders & handrails conditions:	Very good
◆ Cameras conditions:	Excellent - no needs repair
◆ Flashing conditions:	Not functioning
◆ Safety belt conditions:	Present and valid
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	No
If No, are control levers protected to accidental functionality? : Yes	
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes

◆ Acoustic alarm works properly: Yes

◆ Boardwalk presence: Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.