

SALES REPORT: LIEBHERR LH40 - SN PZK100### - Year 2017

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: LH40

Family: WHEEL EXCAVATOR

Serial Number: PZK100###

Order Number MU/MM: MU00837098

Construction year: 2017

Hour meter: 13487

General residual conditions Truck/Tyres: 10 %

Machine main application: Industry - not corrosive field

Machine availability date : 07/08/2026

Location: Coming in

Rating: ★★☆☆☆

MACHINE CONFIGURATION


• Machine type Material Handling MH • Boom type Mono boom • Boom check valves • Stick check valves • Plant features Versatility • Bucket / Grapple Grapple Polipo 5 chele 800l • Tyres type Twin Wheel • General Tyres Residual 10 12.00 20 Liebherr • Stabilizers 4 Stabilizers • Cabin type Hydraulic lift • Cabin fog Front superiore • Air Conditioning system • Auto lube system • Product Link • Antitheft alarm • 41000 Kg • • CE Mark • CE Certificate • EPA Tag • Use and maintenance manual • Registration book & Licence plate No Registration book & Licence plate



MACHINE PHOTOS


◆ Il contaore e':

Funzionante













GENERAL APPEARANCE

◆ Painting Conditions	Good
◆ Counterweight conditions	Good
	Needs painting? : No
◆ Frame / Bumper conditions	Good

Tyres

◆ N/D	10
◆ N/D	10

Right side

◆ N/D	Good
◆ N/D	Good

Left side

◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ Hood / Armor bottom conditions	Present and intact

Functionality

Engine & electrical system functionality

◆ N/D	Accesa e funzionante "al lavoro"
◆ N/D	Good
◆ N/D	No
◆ N/D	No
◆ N/D	No
◆ N/D	No
◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ N/D	No

Functionality drive and rotation

◆ N/D	Good
-------	------

◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
	Presence of leaks : No
◆ N/D	Good
	Presence of leaks : No
◆ N/D	No
Linkage Group	
◆ N/D	Yes
◆ N/D	Good
	Presence of welding/cracks : No
◆ N/D	Good
	Presence of welding/cracks : No
◆ N/D	Good
◆ N/D	Good
	Leaks : No
◆ N/D	Good
	Leaks : No
◆ N/D	Good
	Leaks : No
◆ N/D	Good
◆ N/D	Good
◆ N/D	Good

◆ N/D	Good
-------	------

◆ N/D	NA - Not applicable
-------	---------------------

◆ N/D	Si
-------	----

Cabin and Tools

◆ Conditions internal cabin	Good
-----------------------------	------

◆ Flashing presents issues	Yes
----------------------------	-----

◆ Lights & Windshield present issues	Presents and functioning
--------------------------------------	--------------------------

◆ Air contidioning & Filters conditions	Presents and functioning
---	--------------------------

◆ Back & side camera conditions	Present and functioning
---------------------------------	-------------------------

Check 81/2008

◆ Condizioni freni:	Buono
---------------------	-------

◆ Condizioni freno di Stazionamento:	Buono
--------------------------------------	-------

◆ Glass conditions	Excellent - no needs repair
--------------------	-----------------------------

◆ Lights conditions	Excellent - no needs repair
---------------------	-----------------------------

◆ Rear view mirrors conditions	Excellent - no needs repair
--------------------------------	-----------------------------

◆ Stepladders & handrails conditions	Good
--------------------------------------	------

◆ Cameras conditions	Excellent - no needs repair
----------------------	-----------------------------

◆ Flashing conditions	Present and functioning
-----------------------	-------------------------

◆ Safety belt conditions	Present and valid
◆ Controls been modified	No
◆ Presence of Exclusion Control Lever	Yes
If No, are control levers protected to accidental functionality? : Yes	
◆ Are Tools Functional & Visible with tag	Yes
◆ Canopy completed and comes with keys and bolt	Yes
◆ All Pipes with no damage e/o scratches	Yes
◆ Batteries box shielded	Yes
◆ Acoustic alarm works properly	Yes
◆ Boardwalk presence	Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.