

SALES REPORT: DOOSAN - DAEWOO DL250#KDAEW - SN 5050349 - Year 2020

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: DL250#KDAEW

Family: SMALL WHEEL LOADER

Serial Number: 5050349

Order Number MU/MM: MU00837780

Construction year: 2020

Hour meter: 2093

General residual conditions Truck/Tyres: 40 %

Machine main application: Landfill

Location: Stock Arezzo

Rating: ★★★★★

Public price: Ask

MACHINE CONFIGURATION


• Machine type Standard - GP • Steering type Command steering • Differential Type Standard • Transmission type Manual • Ride Control • Auxiliary Systems • Bucket Ditch Cleaning Bucket 3.5 Get Cover Blade • Tyres type Standard • General Tyres Residual 40 20.5 brigestone • Rops Close • Air Conditioning system • Auto Lube system • 15000 Kg • CE Mark • CE Certificate • Use and maintenance manual • Registration book & Licence plate Registration book & Licence plate


MACHINE PHOTOS

◆ Il contaore e':


Funzionante













GENERAL APPEARANCE

◆ Painting Conditions:	Very Good
◆ Counterweight conditions:	Very good
	Needs painting? : No
◆ Frame/Bumper conditions:	Very Good
◆ Door conditions:	Very good
◆ Central joint:	Very good
◆ Fender/Mudguard conditions:	Very good

Tyres

◆ N/D	40
◆ N/D	40

Functionality

Engine & electrical system functionality

◆ N/D	Spenta e ferma
◆ N/D	Very good
◆ N/D	No
◆ N/D	No
◆ N/D	No
◆ N/D	No
◆ N/D	Very good
◆ N/D	Very good
◆ N/D	Very good
◆ N/D	No
◆ N/D	macchina con batteria scarica, il cliente conferma che il mezzo meccanicamente è in piena efficienza

Functionality drive and rotation

◆ N/D	Very good
◆ N/D	Very good
◆ N/D	Very good
◆ N/D	Very good
	Presence of leaks : No
◆ N/D	Very Good

Engine & electrical system functionality

◆	N/D	Good
---	-----	------

◆	N/D	Good
---	-----	------

◆	N/D	Good
---	-----	------

Linkage Group

◆	N/D	No
---	-----	----

◆	N/D	Very good
---	-----	-----------

Presence of welding/cracks : No

◆	N/D	Good
---	-----	------

◆	N/D	Good
---	-----	------

◆	N/D	Good
---	-----	------

◆	N/D	Good
---	-----	------

◆	N/D	Good
---	-----	------

◆	N/D	NA - Not applicable
---	-----	---------------------

◆	N/D	Si
---	-----	----

Cabin and Tools

◆	Conditions internal cabin:	Good
---	----------------------------	------

◆	Lights & Windshield present issues:	Presents and functioning
---	-------------------------------------	--------------------------

◆	Air contidioning & Filters conditions:	Presents and functioning
---	--	--------------------------

◆ Back & side camera conditions: Present and functioning

Check 81/2008

◆ Condizioni freni: Buono

◆ Condizioni freno di Stazionamento: Buono

◆ Glass conditions: Excellent - no needs repair

◆ Lights conditions: Excellent - no needs repair

◆ Condizioni specchietti: Eccellente - non necessita riparazione

◆ Stepladders & handrails conditions: Good

◆ Cameras conditions: Excellent - no needs repair

◆ Flashing conditions: Present and functioning

◆ Safety belt conditions: Present and expired

◆ Controls been modified: No

◆ Presence of Exclusion Control Lever: Yes

◆ Are Tools Functional & Visible with tag: Yes

◆ Canopy completed and comes with keys and bolt: Yes

◆ All Pipes with no damage e/o scratches: No

◆ Batteries box shielded: Yes

◆ Acoustic alarm works properly: Yes

◆ Boardwalk presence: Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.