

SALES REPORT: OM SPA APOLLO#KOFME - SN 99D076### - Year 2004

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: APOLLO#KOFME

Family: CRUSHERS

Serial Number: 99D076###

Order Number MU/MM: MU00838921

Construction year: 2004

Hour meter: 10380

General residual conditions Truck/Tyres: %

Machine main application:

Machine availability date : 01/08/2026

Location: Coming in

Rating: ★★☆☆☆

Public price: 90.000 €

MACHINE CONFIGURATION

● Machine type Standard ● undefined ● ● ● 400000 Kg ● CE Mark ● CE Certificate

ORIGINS & APPLICATION



◆ Machine Origins:

Consignment

MACHINE PHOTOS



◆ Il contaore e':

Rotto













GENERAL APPEARANCE

◆ Painting Conditions

Poor

FRANTOIO

◆ N/D

Good

◆ N/D	Buono
◆ N/D	Scarso
◆ N/D	10
◆ N/D	10
◆ N/D	Scarso

NASTRI

◆ N/D	Buono
◆ N/D	Scarso
◆ N/D	Buono
◆ N/D	Non Funzionante

CARRO

◆ N/D	Buono
-------	-------

Functionality

◆ In quale stato è stata visionata la macchina:	Accesa e funzionante "al lavoro"
---	----------------------------------

Engine & electrical system functionality

◆ N/D	Good
◆ N/D	No

◆ N/D	No
◆ N/D	No
◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ N/D	Presente

If present, add details : SPIE IN GENERE E MANOMETRI ROTTI

Functionality drive and rotation

◆ N/D	Good
◆ N/D	Good

Linkage Group

◆ N/D	Good
◆ N/D	Poor

Presenza di perdite? Se si, specificare da dove : PACKING E TUBAZIONI

Check 81/2008

◆ Lights conditions:	Broken or Chipped - needs repair
◆ Condizioni specchietti:	Rotto o Scheggiato - necessita riparazione
◆ Stepladders & handrails conditions:	Poor
◆ Cameras conditions:	Broken or Chipped - needs repair

◆ Flashing conditions:	Not functioning
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
If No, are control levers protected to accidental functionality? : Yes	
◆ Are Tools Functional & Visible with tag:	No
◆ Canopy completed and comes with keys and bolt:	No
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	No
◆ Boardwalk presence:	Present and bashee

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.