

SALES REPORT: ALTRE MARCHE HX195 - SN 25### - Year 2019

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: HX195

Family: POMPE AUTOCARRATE

Serial Number: 25###

Order Number MU/MM: MU00839944

Construction year: 2019

Hour meter: 2569

General residual conditions Truck/Tyres: 50 %

Machine main application:

Machine availability date : 27/07/2026

Location: Coming in

Rating: ★★☆☆☆

Public price: Ask


MACHINE CONFIGURATION



• Machine type Standard - GP • Auxiliary Systems undefined • 3500 Kg • CE Mark • CE Certificate • Use and maintenance manual • Registration book & Licence plate Registration book & Licence plate • Auto Lube system

HOUR METER & PHOTOS

◆ Il contachilometri è:

Funzionante







GENERAL APPEARANCE

◆ Painting Conditions:	Good
◆ Counterweight conditions:	Good
◆ Condizioni Assali posteriori:	Buono
◆ Frame/Bumper conditions:	Good

◆ Fender/Mudguard conditions:	Good
-------------------------------	------

Tyres

◆ N/D	70
-------	----

◆ N/D	70
-------	----

Functionality

◆ In quale stato è stata visionata la macchina:	Accesa e provata per ispezione
---	--------------------------------

◆ Engine working conditions:	Good
------------------------------	------

◆ Engine with oil leaks:	No
--------------------------	----

◆ Engine presents blowby:	No
---------------------------	----

◆ Oil-Water presence:	No
-----------------------	----

◆ Engine present smokiness:	No
-----------------------------	----

◆ Radiator conditions:	Good
------------------------	------

◆ Starter motor conditions:	Good
-----------------------------	------

◆ Batteries/Cables conditions:	Good
--------------------------------	------

◆ Presence of electrical fault:	No
---------------------------------	----

◆ Condizioni di funzionamento trasmissione:	Buono
---	-------

◆ Condizioni di funzionamento frizione:	Buono
---	-------

◆ Condizioni Freni(servizio/stazionamento/emergenza):	Buono
---	-------

Check 81/2008

◆ Lights conditions:	Excellent - no needs repair
◆ Condizioni vetri e specchietti	Eccellente - non necessita riparazione
◆ Controls been modified:	Yes
◆ Presence of Exclusion Control Lever:	No
	If No, are control levers protected to accidental functionality? : Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.