

SALES REPORT: CATERPILLAR MH3022 - SN FB300216 - Year 2017

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: MH3022

Family: WHEEL EXCAVATOR

Serial Number: FB300216

Order Number MU/MM: MU00840314

Construction year: 2017

Hour meter: 6438

General residual conditions Truck/Tyres: 50 %

Machine main application: Basic application

Location: Stock Milano Usato

Rating: ★☆☆☆☆

Public price: Ask

MACHINE CONFIGURATION

• Machine type Standard • Boom type Triple boom • Boom check valves • Stick check valves • Plant features Versatility • Bucket / Grapple Standard polipo Get Cover Blade • Tyres type Twin Wheel • General Tyres Residual 50 50 50 Need to replace • Stabilizers 4 Stabilizers • Cabin type Fixed standard • Cabin fog Front • Air Conditioning system Operation No • Auto lube system Operation No • Product Link • 4173 Kg • CE Mark • Use and maintenance manual • Registration book & Licence plate No Registration book & Licence plate


MACHINE PHOTOS

◆ Il contaore e':


Funzionante
















GENERAL APPEARANCE

◆ Painting Conditions	Poor
◆ Counterweight conditions	Good
	Needs painting? : Yes
◆ Frame / Bumper conditions	Good

Tyres

◆ N/D	50
◆ N/D	50

Right side

◆ N/D	Good
-------	------

◆	N/D	Good
---	-----	------

Left side

◆	N/D	Good
---	-----	------

◆	N/D	Good
---	-----	------

◆	N/D	Good
---	-----	------

◆	Hood / Armor bottom conditions	Present and bash
---	--------------------------------	------------------

Functionality

Engine & electrical system functionality

◆	N/D	Non funzionante
---	-----	-----------------

◆	N/D	Poor
---	-----	------

◆	N/D	Yes
---	-----	-----

If Yes, where : Lower chases

◆	N/D	Yes
---	-----	-----

◆	N/D	No
---	-----	----

◆	N/D	No
---	-----	----

◆	N/D	Good
---	-----	------

◆	N/D	Good
---	-----	------

◆	N/D	Not working
---	-----	-------------

◆	N/D	No
---	-----	----

If present, add details : La batteria deve essere sostituita affinché possiamo individuare il problema

Functionality drive and rotation

◆ N/D	Not working
◆ N/D	Not working
◆ N/D	Not working
◆ N/D	NA - Not applicable
◆ N/D	NA - Not applicable
	Presence of leaks : No
◆ N/D	Good
	Presence of leaks : Yes
◆ N/D	No

Linkage Group

◆ N/D	Yes
◆ N/D	Good
	Presence of welding/cracks : No
◆ N/D	Good
	Presence of welding/cracks : No
◆ N/D	Poor
◆ N/D	Good
	Leaks : No
◆ N/D	Good
	Leaks : No

◆ N/D	Good
	Leaks : No
◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ N/D	NA - Not applicable
◆ N/D	Sì
◆ N/D	Sostituire il grasso

Cabin and Tools

◆ Conditions internal cabin	Good
◆ Flashing presents issues	No
◆ Lights & Windshield present issues	Present and not functioning
◆ Air conditioning & Filters conditions	Present and not functioning
◆ Back & side camera conditions	Present and not functioning

Check 81/2008

◆ Condizioni freni:	Buono
◆ Condizioni freno di Stazionamento:	Buono
◆ Glass conditions	Excellent - no needs repair

◆ Lights conditions	Broken or Chipped - needs repair
◆ Rear view mirrors conditions	Broken or Chipped - needs repair
◆ Stepladders & handrails conditions	Good
◆ Cameras conditions	Excellent - no needs repair
◆ Flashing conditions	Present and not functioning
◆ Safety belt conditions	Present and expired
◆ Controls been modified	No
◆ Presence of Exclusion Control Lever	Yes
◆ Are Tools Functional & Visible with tag	Yes
◆ Canopy completed and comes with keys and bolt	Yes
◆ All Pipes with no damage e/o scratches	No
◆ Batteries box shielded	Yes
◆ Acoustic alarm works properly	No
◆ Boardwalk presence	Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.