

## SALES REPORT: CATERPILLAR 262D - SN RE500### - Year 2019

This Report is a summary about observations came out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

#### MACHINE DATA

---

**Model:** 262D

**Family:** SKID STEER LOADER

**Serial Number:** RE500###

**Order Number MU/MM:** MU00840319

**Construction year:** 2019

**Hour meter:** 3563

**General residual conditions Truck/Tyres:** 70 %

**Machine main application:** Basic application

**Machine availability date :** 28/07/2026

**Location:** Coming in

**Rating:** ★★☆☆☆

**Public price:** Ask

#### MACHINE CONFIGURATION

---

• Machine type Wasting configuration • Rops Close • Plant features • General Truck Residual 70% • Air Conditioning system • Product Link • 3760 Kg • CE Mark • CE Certificate • EPA Tag • Use and maintenance manual • undefined

## MACHINE PHOTOS



---

◆ Il contaore e':

Funzionante







|   |                     |      |
|---|---------------------|------|
| ◆ | Painting Conditions | Good |
|---|---------------------|------|

|   |                          |      |
|---|--------------------------|------|
| ◆ | Counterweight conditions | Good |
|---|--------------------------|------|

|  |                      |
|--|----------------------|
|  | Needs painting? : No |
|--|----------------------|

|   |                         |      |
|---|-------------------------|------|
| ◆ | Frame/Bumper conditions | Good |
|---|-------------------------|------|

|   |                        |      |
|---|------------------------|------|
| ◆ | Door conditions (left) | Good |
|---|------------------------|------|

### Truck

|   |     |    |
|---|-----|----|
| ◆ | N/D | 80 |
|---|-----|----|

|   |     |    |
|---|-----|----|
| ◆ | N/D | 80 |
|---|-----|----|

### Functionality

#### Engine & electrical system functionality

|   |     |                                |
|---|-----|--------------------------------|
| ◆ | N/D | Accesa e provata per ispezione |
|---|-----|--------------------------------|

|   |     |      |
|---|-----|------|
| ◆ | N/D | Good |
|---|-----|------|

|   |     |    |
|---|-----|----|
| ◆ | N/D | No |
|---|-----|----|

|   |     |    |
|---|-----|----|
| ◆ | N/D | No |
|---|-----|----|

|   |     |    |
|---|-----|----|
| ◆ | N/D | No |
|---|-----|----|

|   |     |    |
|---|-----|----|
| ◆ | N/D | No |
|---|-----|----|

|   |     |      |
|---|-----|------|
| ◆ | N/D | Good |
|---|-----|------|

|   |     |      |
|---|-----|------|
| ◆ | N/D | Good |
|---|-----|------|

|   |     |      |
|---|-----|------|
| ◆ | N/D | Good |
|---|-----|------|

|       |  |    |
|-------|--|----|
| ◆ N/D |  | No |
|-------|--|----|

---

**Functionality drive and rotation**

|       |  |      |
|-------|--|------|
| ◆ N/D |  | Good |
|-------|--|------|

|       |  |      |
|-------|--|------|
| ◆ N/D |  | Good |
|-------|--|------|

|       |  |      |
|-------|--|------|
| ◆ N/D |  | Good |
|-------|--|------|

|       |  |      |
|-------|--|------|
| ◆ N/D |  | Good |
|-------|--|------|

---

**Linkage Group**

|       |  |    |
|-------|--|----|
| ◆ N/D |  | No |
|-------|--|----|

|       |  |      |
|-------|--|------|
| ◆ N/D |  | Good |
|-------|--|------|

Presence of welding/cracks : No

|       |  |      |
|-------|--|------|
| ◆ N/D |  | Good |
|-------|--|------|

|       |  |      |
|-------|--|------|
| ◆ N/D |  | Good |
|-------|--|------|

|       |  |      |
|-------|--|------|
| ◆ N/D |  | Good |
|-------|--|------|

|       |  |      |
|-------|--|------|
| ◆ N/D |  | Good |
|-------|--|------|

|       |  |      |
|-------|--|------|
| ◆ N/D |  | Good |
|-------|--|------|

|       |  |    |
|-------|--|----|
| ◆ N/D |  | No |
|-------|--|----|

---

**Cabin and Tools**

|                              |  |      |
|------------------------------|--|------|
| ◆ Conditions internal cabin: |  | Good |
|------------------------------|--|------|

|                                       |                          |
|---------------------------------------|--------------------------|
| ◆ Lights & Windshield present issues_ | Presents and functioning |
|---------------------------------------|--------------------------|

|                                          |                          |
|------------------------------------------|--------------------------|
| ◆ Air contidioning & Filters conditions: | Presents and functioning |
|------------------------------------------|--------------------------|

|                                  |                         |
|----------------------------------|-------------------------|
| ◆ Back & side camera conditions: | Present and functioning |
|----------------------------------|-------------------------|

## Check 81/2008

|                       |                             |
|-----------------------|-----------------------------|
| ◆ Glasses conditions: | Excellent - no needs repair |
|-----------------------|-----------------------------|

|                      |                             |
|----------------------|-----------------------------|
| ◆ Lights conditions: | Excellent - no needs repair |
|----------------------|-----------------------------|

|                           |                                        |
|---------------------------|----------------------------------------|
| ◆ Condizioni specchietti: | Eccellente - non necessita riparazione |
|---------------------------|----------------------------------------|

|                                       |      |
|---------------------------------------|------|
| ◆ Stepladders & handrails conditions: | Good |
|---------------------------------------|------|

|                       |                             |
|-----------------------|-----------------------------|
| ◆ Cameras conditions: | Excellent - no needs repair |
|-----------------------|-----------------------------|

|                        |                         |
|------------------------|-------------------------|
| ◆ Flashing conditions: | Present and functioning |
|------------------------|-------------------------|

|                           |                   |
|---------------------------|-------------------|
| ◆ Safety belt conditions: | Present and valid |
|---------------------------|-------------------|

|                           |    |
|---------------------------|----|
| ◆ Controls been modified: | No |
|---------------------------|----|

|                                        |     |
|----------------------------------------|-----|
| ◆ Presence of Exclusion Control Lever: | Yes |
|----------------------------------------|-----|

|                                            |     |
|--------------------------------------------|-----|
| ◆ Are Tools Functional & Visible with tag: | Yes |
|--------------------------------------------|-----|

|                                                  |     |
|--------------------------------------------------|-----|
| ◆ Canopy completed and comes with keys and bolt: | Yes |
|--------------------------------------------------|-----|

|                                           |     |
|-------------------------------------------|-----|
| ◆ All Pipes with no damage e/o scratches: | Yes |
|-------------------------------------------|-----|

|                           |     |
|---------------------------|-----|
| ◆ Batteries box shielded: | Yes |
|---------------------------|-----|

|                                 |     |
|---------------------------------|-----|
| ◆ Acustic alarm works properly: | Yes |
|---------------------------------|-----|

|                       |                         |
|-----------------------|-------------------------|
| ◆ Boardwalk presence: | Present and functioning |
|-----------------------|-------------------------|

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.