

## SALES REPORT: CATERPILLAR 226D - SN HRD02### - Year 2017

This Report is a summary about observations came out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

#### MACHINE DATA

---

**Model:** 226D

**Family:** SKID STEER LOADER

**Serial Number:** HRD02###

**Order Number MU/MM:** MU00841223

**Construction year:** 2017

**Hour meter:** 6365

**General residual conditions Truck/Tyres:** 20 %

**Machine main application:** Basic application

**Machine availability date :** 07/08/2026

**Location:** Coming in

**Rating:** ★★☆☆☆

**Public price:** Ask

#### MACHINE CONFIGURATION

---

• Machine type Wasting configuration • Rops Open • Bucket Standard Get Cover Blade • Plant features • General Truck Residual 20% • Product Link • 2800 Kg • CE Mark • CE Certificate • undefined AK Y755

## MACHINE PHOTOS


---

◆ Il contaore e':

Funzionante









## GENERAL APPEARANCE

|                            |                      |
|----------------------------|----------------------|
| ◆ Painting Conditions      | Good                 |
| ◆ Counterweight conditions | Good                 |
|                            | Needs painting? : No |
| ◆ Frame/Bumper conditions  | Good                 |
| ◆ Door conditions (left)   | Good                 |

### Truck

|       |    |
|-------|----|
| ◆ N/D | 20 |
| ◆ N/D | 20 |

## Functionality

### Engine & electrical system functionality

|       |                                |
|-------|--------------------------------|
| ◆ N/D | Accesa e provata per ispezione |
| ◆ N/D | Poor                           |
| ◆ N/D | No                             |
| ◆ N/D | No                             |
| ◆ N/D | No                             |
| ◆ N/D | No                             |
| ◆ N/D | Good                           |
| ◆ N/D | Good                           |
| ◆ N/D | Good                           |
| ◆ N/D | Sì                             |

### Functionality drive and rotation

|       |      |
|-------|------|
| ◆ N/D | Good |
| ◆ N/D | Good |
| ◆ N/D | Good |
| ◆ N/D | Good |

### Linkage Group

|       |                                 |
|-------|---------------------------------|
| ◆ N/D | No                              |
| ◆ N/D | Good                            |
|       | Presence of welding/cracks : No |
| ◆ N/D | Poor                            |
| ◆ N/D | Good                            |
| ◆ N/D | Good                            |
| ◆ N/D | Good                            |
| ◆ N/D | Good                            |
| ◆ N/D | No                              |

## Cabin and Tools

|                                          |                             |
|------------------------------------------|-----------------------------|
| ◆ Conditions internal cabin:             | Poor                        |
| ◆ Lights & Windshield present issues_    | Present and not functioning |
| ◆ Air conditioning & Filters conditions: | Not functioning             |
| ◆ Back & side camera conditions:         | Not functioning             |

## Check 81/2008

|                           |                                            |
|---------------------------|--------------------------------------------|
| ◆ Glasses conditions:     | Excellent - no needs repair                |
| ◆ Lights conditions:      | Broken or Chipped - needs repair           |
| ◆ Condizioni specchietti: | Rotto o Scheggiato - necessita riparazione |

|                                                  |                         |
|--------------------------------------------------|-------------------------|
| ◆ Stepladders & handrails conditions:            | Poor                    |
| ◆ Cameras conditions:                            | Non presente            |
| ◆ Flashing conditions:                           | Not functioning         |
| ◆ Safety belt conditions:                        | Present and expired     |
| ◆ Controls been modified:                        | No                      |
| ◆ Presence of Exclusion Control Lever:           | Yes                     |
| ◆ Are Tools Functional & Visible with tag:       | Yes                     |
| ◆ Canopy completed and comes with keys and bolt: | Yes                     |
| ◆ All Pipes with no damage e/o scratches:        | No                      |
| ◆ Batteries box shielded:                        | Yes                     |
| ◆ Acoustic alarm works properly:                 | No                      |
| ◆ Boardwalk presence:                            | Present and functioning |

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.