

SALES REPORT: SOCOMEC DMS530#KSOCO - SN 0818530271 - Year 2018

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: DMS530#KSOCO

Family: HYDRAULIC HAMMER

Serial Number: 0818530271

Order Number MU/MM: MU00843989

Construction year: 2018

Hour meter: 1

General residual conditions Truck/Tyres: %

Machine main application: Basic application

Location: Stock Off.Buniotto

Rating: ★★☆☆☆

Public price: Ask

MACHINE CONFIGURATION

● Peak type Conical ● Saddle attachment ● Hydraulic pipes ● 500 Kg ● CE Mark ● CE Certificate

MACHINE PHOTOS

◆ Il contaore è:

Rotto





GENERAL APPEARANCE

- | | |
|----------------------------|------|
| ◆ Painting Conditions | Good |
| <hr/> | |
| ◆ Frame/Bumper conditions: | Good |
| <hr/> | |

Functionality

- | | |
|---|--------------------------------|
| ◆ In quale stato è stata visionata la macchina: | Accesa e provata per ispezione |
| <hr/> | |
| ◆ Engine with oil leaks: | No |
| <hr/> | |
| ◆ Engine working conditions: | Good |
| <hr/> | |
| ◆ Verifica usura/gioco boccola punta: | Buono |
| <hr/> | |

Check 81/2008

- | | |
|--|----|
| ◆ Controls been modified: | No |
| <hr/> | |
| ◆ Are Tools Functional & Visible with tag: | No |
| <hr/> | |

◆ Canopy completed and comes with keys and bolt: Yes

◆ All Pipes with no damage e/o scratches: Yes

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.

Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.

Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".

Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo.

Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues.

Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.

Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.

No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".

Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one.

Main components-with 70/80% of life residue. Machine in security conditions.