

SALES REPORT: ALTRE LINEE LSH12PS#KALTR - SN LS6814### - Year 2023

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: LSH12PS#KALTR

Family: HYDRAULIC HAMMER

Serial Number: LS6814###

Order Number MU/MM: MU00844889

Construction year: 2023

Hour meter: 1

General residual conditions Truck/Tyres: %

Machine main application: Basic application

Machine availability date : 16/09/2026

Location: Coming in

Rating: ★★☆☆☆

Public price: Ask

MACHINE CONFIGURATION

● Peak type Conical ● Saddle attachment ● Hydraulic pipes ● 140 Kg ● CE Mark ● CE Certificate

MACHINE PHOTOS

GENERAL APPEARANCE

◆ Painting Conditions	Good
-----------------------	------

◆ Frame/Bumper conditions:	Good
----------------------------	------

Functionality

◆ In quale stato è stata visionata la macchina:	Accesa e provata per ispezione
---	--------------------------------

◆ Engine with oil leaks:	No
--------------------------	----

◆ Engine working conditions:	Good
------------------------------	------

◆ Verifica usura/gioco boccola punta:	Buono
---------------------------------------	-------

Check 81/2008

◆ Controls been modified:	No
---------------------------	----

◆ Are Tools Functional & Visible with tag:	Yes
--	-----

◆ Canopy completed and comes with keys and bolt:	Yes
--	-----

◆ All Pipes with no damage e/o scratches:	Yes
---	-----

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.