SALES REPORT: CATERPILLAR AP300 - SN B2Y00### - Year 2009

This Report is a summary about observations cames out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: AP300

Family: ASPHALT PAVERS

Serial Number: B2Y00###

Order Number MU/MM: MU00846833

Construction year: 2009

Hour meter: 3928

General residual conditions Truck/Tyres: %

Machine main application:

Location: Coming in

Rating: ★☆☆☆☆

Public price: Ask

MACHINE CONFIGURATION

● Machine type Mass Excavator ● Boom type undefined ● Boom check valves ● Truck type ● Product Link undefined non girevoli ● EPA Tag ● 8000 Kg ● CE Mark

MACHINE PHOTOS

- Hour Meter is: Broken

Replaced reading : 6000






15



















GENERAL APPEARANCE

Painting Conditions	Poor
Spar conditions:	Poor
Residual % - Tyres/Track:	30
Residual % - Cushion:	30

Seat condition:	Poor
Engine working conditions:	Good
Radiator conditions:	Good
Batteries/Cables conditions:	Poor

Functionality

SCREED

N/D	1750 - 3400
N/D	25
N/D	1
N/D	30
N/D	1
N/D	20
N/D	Non presenti

Engine & electrical system functionality

N/D	Spenta e ferma
N/D	Good
N/D	No
N/D	No

- N/D — No
- N/D — Good
- N/D — Good
- N/D — Good
- N/D — No

Functionality drive and rotation

- N/D — Good
- N/D — Good
- N/D — Good

Linkage Group

- N/D — Poor

  Presenza di perdite? Se si, specificare da dove: : No
- N/D — Good

  Presenza di perdite? Se si, specificare da dove: : No
- N/D — Good

  Presenza di perdite? Se si, specificare da dove: : No
- N/D — NA - Not applicable

Check 81/2008

- Condizioni freni: — Buono

Condizioni freno di Stazionamento:	Buono
Lights conditions:	Excellent - no needs repair
Condizioni specchietti:	Mancanti
Stepladders & handrails conditions:	Good
Cameras conditions:	Broken or Chipped - needs repair
Flashing conditions:	Not functioning
Controls been modified:	No
Presence of Exclusion Control Lever:	Yes
Are Tools Functional & Visible with tag:	Yes
Canopy completed and comes with keys and bolt:	Yes
All Pipes with no damage e/o scratches:	No
Batteries box shielded:	Yes
Acustic alarm works properly:	Yes
Boardwalk presence:	Present and functioning

Valutazione Macchina

★ **Non Funzionante (NF)**

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ **Scarso (S)**

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ **Buono (B)**

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.
Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ **Molto Buono (O)**

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.
Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".
Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ **Eccellente (E)**

La macchina si presenta in condizioni eccellenti, prossime al nuovo.
Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ **Not Working (NW)**

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ **Poor (P)**

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ **Good (G)**

Machine is in good condition and operational, with no structural issues.
Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.
Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ **Very Good (VG)**

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.
No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".
Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ **Excellent (E)**

Machine is in excellent condition, comparable to a new one.
Main components with 70/80% of life residue. Machine in security conditions.