

SALES REPORT: TAKEUCHI TB210R - SN 211006166 - Year 2021

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: TB210R

Family: MINI EXCAVATOR

Serial Number: 211006166

Order Number MU/MM: MU00846898

Construction year: 2021

Hour meter: 1184

General residual conditions Truck/Tyres: 70 %

Machine main application: Basic application

Location: Stock Off. Madaschi

Rating: ★★☆☆☆

Public price: Ask

MACHINE CONFIGURATION

• Machine type Standard • Boom type Mono boom • Plant features Hammer/Crusher line • Quick coupler Mechanic Klac • Bucket Standard pulizia canali 2 • Truck type Hydraulic extendible • Blade • General Truck Residual 69% • Cabin type Fixed standard • 1150 Kg • CE Mark • CE Certificate

MACHINE PHOTOS

◆ Il contaore è:

Funzionante







GENERAL APPEARANCE

Painting Conditions	Poor
Counterweight conditions:	Good
Frame/Bumper conditions:	Good

TRUCK

N/D	70
N/D	70
N/D	70
N/D	60

Right side

◆ N/D	Good
◆ N/D	Good

Left side

◆ N/D	Good
◆ N/D	Good
◆ N/D	Good
◆ Hood/Armor bottom conditions:	Present and intact

Functionality

Engine & electrical system functionality

◆ N/D	Accesa e provata per ispezione
◆ N/D	Good
◆ N/D	No
◆ N/D	No
◆ N/D	No
◆ N/D	No
◆ N/D	Good
◆ N/D	Good

◆ N/D	Poor
-------	------

◆ N/D	Si
-------	----

Functionality drive and rotation

◆ N/D	Good
-------	------

◆ N/D	Good
-------	------

◆ N/D	Good
-------	------

◆ N/D	Good
-------	------

◆ N/D	Good
-------	------

Presence of leaks : No

◆ N/D	Good
-------	------

Presence of leaks : No

Linkage Group

◆ N/D	No
-------	----

◆ N/D	Good
-------	------

Presence of welding/cracks : No

◆ N/D	Good
-------	------

Presence of welding/cracks : No

◆ N/D	Good
-------	------

◆ N/D	Good
-------	------

Leaks : No

◆ N/D	Good
-------	------

Leaks : No

◆ N/D	Good
	Leaks : No
◆ N/D	Good
◆ N/D	Good
◆ N/D	Poor
◆ N/D	Good
◆ N/D	Good
◆ N/D	No

Cabin and Tools

◆ Conditions internal cabin:	Good
◆ Flashing presents issues:	No
◆ Lights & Windshield present issues:	Not presents
◆ Air conditioning is working:	Non Presente
◆ Back & side camera conditions:	Not functioning

Check 81/2008

◆ Glass conditions:	Excellent - no needs repair
◆ Lights conditions:	Broken or Chipped - needs repair
◆ Rear view mirrors conditions:	Mancanti
◆ Stepladders & handrails conditions:	Good

◆ Cameras conditions:	Broken or Chipped - needs repair
◆ Flashing conditions:	Not functioning
◆ Safety belt conditions:	Present and valid
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	No
◆ Boardwalk presence:	Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.